

Standard and special equipment
Model year :

801+051

Sales Release :

2021-01-19

Production Change :

2021-03-01

Legend

(*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National

Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

CLS Coupé

Code	equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
B28	AMG Exterior Carbon-Fibre package II		-	-	-	-	-	●	1.837,50
		Not in conjunction with U47						*	
		Only in conjunction with U93						*	
P31	Mercedes-AMG exterior		-	-	-	-	-	S	0,00
		Includes codes 489+772+RRE [RRF/RTY/RTZ/RVO/RVP/RZU]+U47 [U93]						*	
P60	AMG Night package		-	-	-	-	-	●	603,75
		i.V.m. Code PYH	-	-	-	-	-	●	341,25
U47	AMG spoiler lip		-	-	-	-	-	S	0,00
		Not in conjunction with B28/U93						*	
U93	AMG spoiler lip in carbon fibre on boot lid		-	-	-	-	-	○	0,00
		Not in conjunction with U47						*	
		Only in conjunction with B28						*	
U95	AMG spoiler lip		○	○	○	○	○	-	0,00
		Not in conjunction with 11R/301A/469/49R/83R/R70/R82/R98/U12							
		Not in conjunction with 301A/818A/U12	*	*	*	*	*		
		Not in conjunction with P14/P15		*	*		*		
		Not in conjunction with U29							
		Not in conjunction with U46							
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*		
		Only in conjunction with P29+P31							
L6G	AMG Performance steering wheel in DINAMICA microfi		-	-	-	-	-	●	514,50
		Not in conjunction with 443/55U/875A/878A/955A/P87						*	
		Only in conjunction with U88						*	
L6J	AMG Performance steering wheel in nappa leather		-	-	-	-	-	S	0,00
L6K	AMG Performance steering wheel in nappa leather / Di		-	-	-	-	-	●	441,00
		Not in conjunction with 55U/875A/955A/P87						*	
L6L	AMG Performance steering wheel in piano lacquer / na		-	-	-	-	-	●	651,00
P29	Mercedes-AMG interior		-	-	-	-	-	S	0,00
		Includes codes 671A [871A/875A/878A]+873 [401/902]+H41 [736/H01/H05/H06/H16/H32/H64/H73]+L6J						*	
250	AMG Driver's package		-	-	-	-	-	●	1.995,00
		Not in conjunction with R05/R66						*	
421	AMG SPEEDSHIFT TCT 9G		-	-	-	-	-	S	0,00
B59	AMG DYNAMIC SELECT		-	-	-	-	-	S	0,00
U78	AMG performance exhaust system, selectable		-	-	-	-	-	●	1.470,00
		i.V.m. Code PYC	-	-	-	-	-	○	0,00
		i.V.m. S-Code 3P8	-	-	-	-	-	○	0,00
P62	designo interior in black / titanium grey pearl		●	●	●	●	●	●	5.145,00
		Includes codes 51U [61U]+951A+H32 [H01/H05/H06/H16/H41/H64/H73]+L5C [L3B]+U04+U38	*	*	*	*	*		
		Includes codes 51U [61U]+951A+H32 [H01/H05/H06/H16/H41/H64/H73]+U04+U38						*	
		Not in conjunction with 201A/204A/205A/208A/211A/261/301A/601A/736/737/801A/804A/805A/808A/887A/955A/U12	*						
		Not in conjunction with 201A/204A/205A/208A/211A/301A/601A/801A/804A/805A/808A/887A/955A/U12							
		Not in conjunction with 304/418/B20/B23/B62/P87/P89/PAQ/U12/U26	*	*	*	*	*	*	
		Not in conjunction with 55U/58U/65U/955A/P87/U26	*						
		Not in conjunction with 55U/58U/65U/P87/U26							
		Not in conjunction with 55U/58U/65U	*	*	*	*	*	*	
		Not in conjunction with 671A/861A/871A/875A/877A/878A/U17/Y05							
		Not in conjunction with U17/Y05						*	
		Only in conjunction with 275+287+P49	*	*	*	*	*	*	
		i.V.m. Code P31	●	●	●	●	●	●	4.882,50

		i.V.m. Code PYN/PYO	●	●	●	●	●	-	2.362,50
		i.V.m. Code PYN/PYO	-	-	-	-	-	●	1.706,25
P87	designo interior in macchiato beige / titan red		●	●	●	●	●	●	5.145,00
		Includes codes 287+55U [65U]+955A+H05 [H01/H06/H16/H32/H41/H64/H73]+L3B+U04+U38							
		Includes codes 287+55U [65U]+955A+H05 [H01/H06/H16/H32/H41/H64/H73]+U04+U38							
		Includes codes 55U [65U]+955A [957A]+H05 [H01/H06/H16/H32/H41/H64/H73]+L3B+U04+U38	*	*	*	*	*		
		Includes codes 55U [65U]+955A+H05 [H01/H06/H16/H32/H41/H64/H73]+U04+U38						*	
		Includes codes U38+U04+L3B+55U [65U]+955A+H05 [H01/H06/H16/H32/H41/H64/H73]	*						
		Not in conjunction with 201A/204A/205A/208A/211A/261/301A/431/601A/736/737/801A/804A/805A/808A/887A/951A/L5C/U12	*						
		Not in conjunction with 201A/204A/205A/208A/211A/301A/431/601A/801A/804A/805A/808A/887A/951A/L5C/U12							
		Not in conjunction with 431/B23/L5C/P62/P89/U12/U26	*	*	*	*	*		
		Not in conjunction with 51U/58U/61U/736	*	*	*	*	*	*	
		Not in conjunction with 51U/58U/61U/951A/P62/U26	*						
		Not in conjunction with 51U/58U/61U/P62/U26							
		Not in conjunction with 671A/861A/871A/875A/877A/878A/L6G/L6K/U17/Y05							
		Not in conjunction with L6G/L6K/U17/Y05						*	
		Only in conjunction with 275+287+P49	*	*	*	*	*	*	
		Only in conjunction with 275+P49							
		Only in conjunction with 428+[955A/957A]	*	*	*	*	*		
		i.V.m. Code P31	●	●	●	●	●	●	4.882,50
		i.V.m. Code PYN/PYO	●	●	●	●	●	-	2.362,50
		i.V.m. Code PYN/PYO	-	-	-	-	-	●	1.706,25
P89	designo interior in a two-tone finish		●	●	●	●	●	-	5.145,00
		Includes codes 418 [B23]+828A [802A/809A/814A/824A/827A/834A]+B62 [U26]	*	*	*	*	*		
		Not in conjunction with 55U/58U/65U/B20/L5C/P14/P15/P62/P87/PAQ/U04/U12	*	*	*	*	*		
		Only in conjunction with 275+287+[802A/809A/814A/824A/827A/828A/834A/RRE/RRF/RVO/RVP/RVR]+P26	*	*	*	*	*		
		Only in conjunction with U95		*	*		*		
		i.V.m. Code PYN	●	●	●	●	●	-	3.034,50
		i.V.m. Code PYO	●	●	●	●	●	-	1.963,50
P55	Night package		●	●	●	●	●	-	603,75
		Includes codes 840 [U50]+R70 [R82/RRF/RVP]	*	*	*	*	*		
		Not in conjunction with 11R/49R/83R/R98	*	*	*	*	*		
		i.V.m. Code P31+840	●	●	●	●	●	-	787,50
		i.V.m. Code P31+U50	●	●	●	●	●	-	525,00
		i.V.m. Code P31+U50	●	●	●	●	●	-	525,00
		i.V.m. Code PYH	●	●	●	●	●	-	829,50
PAQ	designo high-pile floor mats and Velour Boot package		●	●	●	●	●	-	829,50
		Includes codes 304+B62	*	*	*	*	*		
		Not in conjunction with 802A/809A/814A/824A/827A/828A/834A/B20/P62/P89/U04/U12/U26	*	*	*	*	*		
4U1	designo roof decals in high-gloss black		●	●	●	●	●	●	829,50
		Only in conjunction with 414	*	*	*	*	*	*	
		available Q4/2020	*	*	*	*	*	*	
260	Omission of model plate on boot lid		○	○	○	○	○	○	0,00
231	Garage door opener		●	●	●	●	●	●	236,25
		Only in conjunction with P49	*	*	*	*	*	*	
871	HANDS-FREE ACCESS		○	○	○	○	○	○	0,00
		Available only as part of (P17)	*	*	*	*	*	*	
		Only in conjunction with P17	*	*	*	*	*	*	
881	Remote boot lid closing		●	●	●	●	●	●	551,25
		i.V.m. Code P17	○	○	○	○	○	○	0,00
883	Power closing		●	●	●	●	●	●	577,50
889	KEYLESS-GO		●	●	●	●	●	●	735,00
		i.V.m. Code P17	○	○	○	○	○	○	0,00
B67	Vehicle key in high-gloss black with ornamental surround		●	●	●	●	●	●	105,00
		Not in conjunction with B68	*	*	*	*	*	*	
B68	Vehicle key in high-gloss white with ornamental surround		●	●	●	●	●	●	105,00
		Not in conjunction with B67	*	*	*	*	*	*	
P17	KEYLESS-GO Comfort package		●	●	●	●	●	●	1.270,50
		Includes codes 871+881+889	*	*	*	*	*	*	
		Includes codes 889+881+871	*						
		i.V.m. Code PYN	○	○	○	○	○	○	0,00
		i.V.m. Code PYO	○	○	○	○	○	○	0,00
297U	designo selenite grey magno		●	●	●	●	●	●	2.940,00
		Only in conjunction with 524	*	*	*	*	*	*	
799U	designo diamond white bright		●	●	●	●	●	●	1.732,50
996U	designo hvacinth red metallic		●	●	●	●	●	●	1.291,50

197U	obsidian black		●	●	●	●	●	●	913,50
831U	graphite grey		●	●	●	●	●	●	913,50
859U	Mojave silver		●	●	●	●	●	●	913,50
890U	cavansite blue		●	●	●	●	●	●	913,50
922U	high-tech silver		●	●	●	●	●	●	913,50
992U	selenite grey		●	●	●	●	●	●	913,50
040U	black		○	○	○	○	○	○	0,00
149U	polar white		●	●	●	●	●	●	315,00
032U	mystic blue metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with U95		*	*		*		
041U	graphite metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with U95		*	*		*		
049U	cashmere white magno		●	●	●	●	●	●	6.195,00
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*	
		Only in conjunction with 235+524+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with U95		*	*		*		
124U	classic grey non-metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with U95		*	*		*		
385U	Côte d'Azur light blue metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with U95		*	*		*		
773U	Teide light grey metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with U95		*	*		*		
825U	classic green non-metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with U95		*	*		*		
904U	classic blue non-metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with U95		*	*		*		
947U	Côte d'Azur dark blue metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with U95		*	*		*		
414	Sliding sunroof		●	●	●	●	●	●	1.181,25
		i.V.m. Code PYO	○	○	○	○	○	○	0,00
E22	Support for roof attachments		●	●	●	●	●	●	441,00
628	Adaptive Highbeam Assist Plus		○	○	○	○	○	○	0,00
		Available only as part of (P35)	*	*	*	*	*	*	
		Not in conjunction with 608/632	*	*	*	*	*	*	
		Not in conjunction with 632	*						
		Only in conjunction with P35	*	*	*	*	*	*	
632	LED High Performance headlamps		○	○	○	○	○	○	0,00
		Not in conjunction with 628/642/P35	*	*	*	*	*	*	
		Not in conjunction with P35							
P35	MULTIBEAM LED		●	●	●	●	●	●	1.522,50

		Includes codes 628+642	*	*	*	*	*	*	*	
		Not in conjunction with 608/632	*	*	*	*	*	*	*	
		Not in conjunction with 632								
		i.V.m. Code PYN/PYO	○	○	○	○	○	○	○	0,00
550	Trailer coupling with ESP[®] trailer stabilisation		●	●	●	●	●	●	●	1.008,00
596	heat-insulating, noise-insulating and infrared-reflecting		○	○	○	○	○	○	○	0,00
		Available only as part of (PAF)	*	*	*	*	*	*	*	
		Not in conjunction with 840	*	*	*	*	*	*	*	
		Only in conjunction with PAF	*	*	*	*	*	*	*	
887	Independent boot locking		●	●	●	●	●	●	●	26,25
E16	Rim lock set		●	●	●	●	●	●	●	52,50
		Only for right hand drive	*	*						
P54	URBAN GUARD vehicle protection		●	●	●	●	●	●	●	493,50
		Includes codes 551+882	*	*	*	*	*	*	*	
		Not in conjunction with 852								
		Not in conjunction with P82	*	*	*	*	*	*	*	
P82	URBAN GUARD vehicle protection Plus		●	●	●	●	●	●	●	703,50
		Includes codes 551+882	*	*	*	*	*	*	*	
		Not in conjunction with P54	*	*	*	*	*	*	*	
R01	Summer tyres		○	○	○	○	○	○	○	0,00
		Not in conjunction with 645/R03	*	*	*	*	*	*	*	
		Not in conjunction with R05							*	
		only in conjunction with 11R/22R/49R/83R/R70/R82/R98/RRE/RRF/RVO/RVP/RVR/RTY/RTZ/RZU	*	*	*	*	*	*	*	
R03	Sports tyres		○	○	○	○	○	○	○	0,00
		Not in conjunction with 469/645/R01/R66/R98/RVO/RVP/RVR								
		Not in conjunction with 469/645/R01/R98/RVO/RVP/RVR	*							
		Not in conjunction with 645/R01/R66/R98/RVO/RVP/RVR	*	*	*	*	*	*	*	
R06	Noise reduced tyre with foam absorber		○	○	○	○	○	○	○	0,00
		Not in conjunction with 469/645/83R/R70								
		Not in conjunction with 469/645/R70	*							
		Not in conjunction with 645/83R/R70	*	*	*	*	*	*	*	
R66	run-flat tyres		●	●	●	●	●	●	●	294,00
		Not in conjunction with 250/RTY/RTZ/RVO/RVP/RZU								
		Not in conjunction with 250							*	
		Not in conjunction with 469/R03								
		Not in conjunction with 469	*							
		Not in conjunction with B51	*	*	*	*	*	*	*	
		Not in conjunction with R03	*	*	*	*	*	*	*	
		Only in conjunction with [RRE/RRF]							*	
		i.V.m. Code PYB	●	●	●	●	●	●	●	241,50
		i.V.m. Code ((RRE/RRF)+R05)	-	-	-	-	-	○	○	0,00
		i.V.m. div. Rädern (19"/20")	○	○	○	○	○	○	-	0,00
RRE	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		●	●	●	●	●	●	-	1.155,00
		Not in conjunction with 11R/261/469/49R/736/737/83R/R70/R82/R98/RVR	*							
		Not in conjunction with 11R/469/49R/83R/R70/R82/R98/RVR								
		Not in conjunction with RRF/RVO/RVP	*							
		Only in conjunction with 776	*	*	*	*	*	*	*	
		i.V.m. Code P31	○	○	○	○	○	○	-	0,00
RRE	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	○	○	0,00
RRF	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	S	S	0,00
RRF	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		●	●	●	●	●	●	-	1.470,00
		Not in conjunction with 11R/261/469/49R/736/737/83R/R70/R82/R98/RVR	*							
		Not in conjunction with 11R/469/49R/83R/R70/R82/R98/RVR								
		Not in conjunction with RRE/RVO/RVP	*							
		Only in conjunction with 776	*	*	*	*	*	*	*	
		i.V.m. Code P31	●	●	●	●	●	●	-	315,00
		i.V.m. Code P31+P55	○	○	○	○	○	○	-	0,00
RTY	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	●	●	1.155,00
		Not in conjunction with R05/R66						*	*	
		Only in conjunction with R01						*	*	
RTZ	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	●	●	1.470,00
		Not in conjunction with R05/R66						*	*	
		Only in conjunction with R01						*	*	
RVO	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels		●	●	●	●	●	●	-	1.995,00
		Not in conjunction with 11R/261/469/49R/645/736/737/83R/B51/R03/R70/R82/R98/RVR	*							

		Not in conjunction with 11R/469/49R/645/83R/B51/R03/R70/R82/R98/RVR											
		Not in conjunction with 645/B51/R03	*	*	*	*	*						
		Not in conjunction with RRE/RRF/RVP	*										
		Only in conjunction with 776+R01	*										
		Only in conjunction with 776+R06+R66	*	*	*	*	*						
		Only in conjunction with R01	*	*	*	*	*						
		Only in conjunction with R06+R66											
		i.V.m. Code P31	●	●	●	●	●	-					945,00
RVO	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels		-	-	-	-	-	●					945,00
		Not in conjunction with R05/R66										*	
		Only in conjunction with R01										*	
RVP	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels		-	-	-	-	-	●					1.260,00
		Not in conjunction with R05/R66										*	
		Only in conjunction with R01										*	
RVP	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels		●	●	●	●	●	-					2.310,00
		Not in conjunction with 11R/469/49R/645/83R/B51/R03/R70/R82/R98/RVR	*										
		Not in conjunction with 645/B51/R03	*	*	*	*	*						
		Not in conjunction with RRE/RRF/RVO	*										
		Only in conjunction with 776+R01	*										
		Only in conjunction with 776+R06+R66	*	*	*	*	*						
		Only in conjunction with R01	*	*	*	*	*						
		Only in conjunction with R06+R66	*										
		i.V.m. Code P31	●	●	●	●	●	-					1.260,00
		i.V.m. Code P31+P55	●	●	●	●	●	-					945,00
RVR	50.8 cm (20-inch) AMG multi-spoke alloy wheels		●	●	●	●	●	-					2.520,00
		Not in conjunction with 11R/201A/204A/205A/208A/211A/301A/469/49R/55U/58U/601A/632/645/656/	*										
		Not in conjunction with 11R/469/49R/645/83R/B51/R03/R70/R82/RRE/RRF/RVO/RVP	*										
		Not in conjunction with 645/B51/R03	*	*	*	*	*						
		Only in conjunction with 776+P29+P31+P35+P49+R01+R06+R66	*										
		Only in conjunction with 776+R01+R06+R66	*	*	*	*	*						
		i.V.m. Code P31	●	●	●	●	●	-					1.470,00
RZU	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	●					1.680,00
		Not in conjunction with R05/R66										*	
		Only in conjunction with R01										*	
11R	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels with		●	●	●	●	●	-					630,00
		Not in conjunction with 032U/041U/049U/124U/211A/385U/601A/772/773U/776/802A/807A/809A/814A/	*	*	*	*	*						
		Not in conjunction with 211A/261/469/49R/601A/736/737/772/776/83R/887A/P29/P31/P55/R70/R82/R98/RRE/RRF/RVO/RVP/RVR/U26/U50/U95	*										
		Not in conjunction with 211A/469/49R/601A/776/83R/887A/P29/P31/P55/R70/R82/R98/RRE/RRF/RVO/RVP/RVR/U26/U50/U95				*		*					
		Not in conjunction with U29				*		*					
		Not in conjunction with U95			*	*		*					
		Only in conjunction with P14+P15	*	*	*	*	*	*					
49R	48.3 cm (19-inch) 5-spoke light-alloy wheels		●	●	●	●	●	-					367,50
		Not in conjunction with 032U/041U/049U/124U/211A/385U/601A/645/772/773U/776/802A/807A/809A/814A/	*	*	*	*	*						
		Not in conjunction with 11R/211A/261/469/601A/645/736/737/772/776/887A/P29/P31/P55/R70/R82/R98/RRE/RRF/RVO/RVP/RVR/U26/U50/U95	*										
		Not in conjunction with U29				*		*					
		Not in conjunction with U95			*	*		*					
		Only in conjunction with P14+P15	*	*	*	*	*	*					
83R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		○	○	○	○	○	-					0,00
		Available only as part of (P15)	*	*	*	*	*	*					
		Not in conjunction with 032U/041U/049U/124U/211A/385U/601A/772/773U/776/802A/807A/809A/814A/	*	*	*	*	*	*					
		Not in conjunction with 11R/211A/261/601A/736/737/772/776/887A/P29/P31/P55/R70/R82/R98/RRE/RRF/RVO/RVP/RVR/U26/U50/U95	*										
		Not in conjunction with 11R/211A/49R/601A/776/887A/P29/P31/P55/R06/R70/R82/R98/RRE/RRF/RVO/RVP/RVR/U26/U50/U95				*		*					
		Not in conjunction with U29				*		*					
		Not in conjunction with U95			*	*		*					
		Only in conjunction with P14+P15	*	*	*	*	*	*					
R70	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	●	●	●	●	-					210,00
		Not in conjunction with 032U/041U/049U/124U/211A/385U/601A/645/772/773U/776/802A/807A/809A/814A/	*	*	*	*	*	*					
		Not in conjunction with 11R/211A/469/49R/601A/645/776/83R/887A/P29/P31/R06/R82/R98/RRE/RRF/RVO/RVP/RVR/U26/U95	*										
		Not in conjunction with U29				*		*					
		Not in conjunction with U95			*	*		*					
		Only in conjunction with P14+P15	*	*	*	*	*	*					
		i.V.m. Code P55	○	○	○	○	○	-					0,00
R82	48.3 cm (19-inch) 5-spoke light-alloy wheels		●	●	●	●	●	-					630,00
		Not in conjunction with 032U/041U/049U/124U/211A/385U/601A/645/772/773U/802A/807A/809A/814A/	*	*	*	*	*	*					
		Not in conjunction with 11R/211A/261/469/49R/601A/645/736/737/772/776/83R/887A/P29/P31/R70/R82/R98/RRE/RRF/RVO/RVP/RVR/U26/U95	*										

		Not in conjunction with 11R/211A/469/49R/601A/645/83R/887A/P29/P31/R70/R98/RRE/RRF/RVO/RVP/RVR/U26/U95								
		Not in conjunction with U29			*		*			
		Not in conjunction with U95		*	*		*			
		Only in conjunction with P14+P15	*	*	*	*	*			
R98	50.8 cm (20-inch) 5-twin-spoke light-alloy wheels		●	●	●	●	●	-		1.470,00
		Not in conjunction with 032U/041U/049U/124U/211A/385U/601A/645/772/773U/802A/807A/809A/814A	*	*	*	*	*			
		Not in conjunction with 11R/211A/261/469/49R/601A/645/736/737/772/776/83R/887A/B51/P29/P31/E	*							
		Not in conjunction with 11R/211A/469/49R/601A/645/83R/887A/B51/P29/P31/R03/R70/R82/RRE/RRF/RVO/RVP/U26/U95								
		Not in conjunction with U29			*		*			
		Not in conjunction with U95		*	*		*			
		Only in conjunction with P14+P15+R01+R06+R66	*	*	*	*	*			
		Only in conjunction with R01+R06+R66	*							
B51	TIREFIT		●	●	●	●	●	●		52,50
		Not in conjunction with R66	*	*	*	*	*	*		
		Not in conjunction with R98/RVO/RVP/RVR	*	*	*	*	*			
		i.V.m. Code PYB	○	○	○	○	○	○		0,00
249	interior mirror and driver's exterior mirror automatical		○	○	○	○	○	○		0,00
		Available only as part of (P49)	*	*	*	*	*	*		
		Only in conjunction with P49	*	*	*	*	*	*		
500	Electrically folding exterior mirrors		○	○	○	○	○	○		0,00
		Available only as part of (P49)	*	*	*	*	*	*		
		Only in conjunction with P49	*	*	*	*	*	*		
540	Electric sunblind for rear window		●	●	●	●	●	●		404,25
597	Windscreen, heated		●	●	●	●	●	●		609,00
		Not in conjunction with 228/865/B24	*	*	*	*	*	*		
840	Heat-insulating dark-tinted glass		●	●	●	●	●	●		409,50
		Not in conjunction with 596/PAF/U50	*							
		Not in conjunction with PAF/U50	*	*	*	*	*	*		
		i.V.m. Code P55	○	○	○	○	○	-		0,00
		i.V.m. Code P60	-	-	-	-	-	○		0,00
		i.V.m. Code PYH	○	○	○	○	○	○		0,00
875	Heated windscreen washer system		●	●	●	●	●	●		178,50
P49	Mirror package		●	●	●	●	●	●		577,50
		Includes codes 249+500	*	*	*	*	*	*		
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○		0,00
PAF	Acoustic Comfort package		●	●	●	●	●	●		1.155,00
		Includes codes 596	*	*	*	*	*	*		
		Not in conjunction with 840	*	*	*	*	*	*		
U50	Omission of heat-insulating dark-tinted glass		○	○	○	○	○	○		0,00
		Not in conjunction with 11R/261/469/49R/736/737/83R/R98/RVR	*							
		Not in conjunction with 11R/469/49R/83R								
		Not in conjunction with 11R/49R/83R/R98	*	*	*	*	*	*		
		Not in conjunction with 840	*	*	*	*	*	*		
		Only in conjunction with P55	*	*	*	*	*	*		
		Only in conjunction with P60						*		
518	Media Interface cable kit		●	●	●	●	●	●		52,50
01U	Preinstallation for Navigation Services		○	○	○	○	○	○		0,00
		Available only as part of (PBF)	*	*	*	*	*	*		
		Only in conjunction with PBF	*	*	*	*	*	*		
355	Extended MBUX functions		○	○	○	○	○	○		0,00
365	Hard-disc navigation		●	●	●	●	●	●		577,50
		i.V.m. Code PBF	○	○	○	○	○	○		0,00
367	Preinstallation for Live Traffic Information		○	○	○	○	○	○		0,00
PBF	Navigation Connectivity package		●	●	●	●	●	●		682,50
		Includes codes 01U+362+365	*	*	*	*	*	*		
		Includes codes 01U								
		Not in conjunction with 513/546/811/865/K32/K33/K34								
		Only in conjunction with 355+367+504+868+876+891+B18								
		i.V.m. Code PYB	○	○	○	○	○	○		0,00
537	Digital radio		○	○	○	○	○	○		0,00
865	TV receiver		●	●	●	●	●	●		1.039,50
		Not in conjunction with 355/504/597/868/PBF	*							
		Not in conjunction with 548/597	*	*	*	*	*	*		
		Only in conjunction with 01U+12U+14U+16U+17U+367+448+513+876+891	*							
		Only in conjunction with 01U+14U+16U+17U+367+448+513+876+891								

		Only in conjunction with 549+868	*	*	*	*	*	*		
866	Preinstallation for entertainment and comfort features		●	●	●	●	●	●		178,50
810	Burmester® surround sound system		●	●	●	●	●	●		892,50
		Not in conjunction with 811	*	*	*	*	*	*		
		Only in conjunction with B18	*	*	*	*	*	*		
		i.V.m. Code PYO	○	○	○	○	○	○		0,00
811	Burmester® high-end 3D surround sound system		●	●	●	●	●	●		5.145,00
		Not in conjunction with 355/504/810/868/B18/PBF	*							
		Not in conjunction with 77B/810/B18	*	*	*	*	*	*		
		Only in conjunction with 01U+12U+14U+16U+17U+367+414+448+513+876+891	*							
		Only in conjunction with 01U+14U+16U+17U+367+414+448+513+876+891								
		Only in conjunction with 414	*	*	*	*	*	*		
		i.V.m. Code PYO	●	●	●	●	●	●		4.252,50
14U	Smartphone integration		●	●	●	●	●	●		420,00
		Only in conjunction with 16U+17U	*	*	*	*	*	*		
897	Wireless charging system for mobile devices in the front		●	●	●	●	●	●		210,00
		Not in conjunction with 274	*	*	*	*	*	*		
		Not in conjunction with 899	*	*	*	*	*	*		
		i.V.m. Code PYB	○	○	○	○	○	○		0,00
899	Multifunction telephony		●	●	●	●	●	●		514,50
		Not in conjunction with 897	*	*	*	*	*	*		
		Only in conjunction with 274	*	*	*	*	*	*		
		i.V.m. Code PYB	●	●	●	●	●	●		304,50
21U	Dash cam		●	●	●	●	●	●		210,00
543	Pull-out sun visor		●	●	●	●	●	●		99,75
U17	Omission of coloured seat belts		-	-	-	-	-	○		0,00
		Not in conjunction with 55U/951A/955A/Y05						*		
		Only in conjunction with U26						*		
U38	Dashboard and door beltlines in nappa leather		●	●	●	●	●	●		735,00
		Not in conjunction with 201A/204A/205A/208A/211A/301A/601A	*	*	*	*	*	*		
		Not in conjunction with 671A						*		
		i.V.m. Code P62/P87	○	○	○	○	○	○		0,00
U67	230 V socket in rear		●	●	●	●	●	●		126,00
Y05	Red seat belts		-	-	-	-	-	S		0,00
		Not in conjunction with 55U/951A/955A/U17						*		
		Only in conjunction with U26						*		
228	Auxiliary heater		●	●	●	●	●	●		1.438,50
		Not in conjunction with 597	*	*	*	*	*	*		
		Only in conjunction with 916	*	*	*					
		Only for left hand drive	*	*	*	*	*	*		
		i.V.m. Code 362	●	●	●	●	●	●		1.281,00
443	Steering wheel heating		●	●	●	●	●	●		273,00
		Not in conjunction with 431/L5C	*	*	*	*	*			
		Not in conjunction with L6G/U88						*		
		Only in conjunction with 275+P49	*	*	*	*	*	*		
		Only in conjunction with 428+L3B	*	*	*	*	*			
580	THERMATIC automatic climate control		S	S	S	S	S	S		0,00
		Not in conjunction with 581/670	*	*	*	*	*	*		
581	THERMOTRONIC automatic climate control		●	●	●	●	●	●		619,50
		Not in conjunction with 580	*	*	*	*	*	*		
		Only in conjunction with 670	*	*	*	*	*	*		
B24	Remote control for auxiliary heating		○	○	○	○	○	○		0,00
		Not in conjunction with 597	*	*	*	*	*	*		
		Only in conjunction with 228	*	*	*	*	*	*		
		Only in conjunction with 916	*	*	*					
		Only for left hand drive	*	*	*	*	*	*		
		i.V.m. Code 362	●	●	●	●	●	●		210,00
P21	AIR-BALANCE package		●	●	●	●	●	●		351,75
		i.V.m. Code PBP/PBR	○	○	○	○	○	○		0,00
P68	Warmth Comfort package		●	●	●	●	●	-		829,50
		Includes codes 902+906	-	-	-	-	-	●		451,50
		Not in conjunction with 301A	*	*	*	*	*	*		
		Not in conjunction with 873	*	*	*	*	*	*		
		Only in conjunction with 275+P49	*	*	*	*	*	*		

		i.V.m. Code PBP	● ● ● ● ● -	451,50
		i.V.m. Code PYN/PYO	● ● ● ● ● -	451,50
		i.V.m. Code PBR	○ ○ ○ ○ ○ ○	0,00
287	EASY-PACK quickfold		● ● ● ● ● ●	456,75
		i.V.m. Code PYB	○ ○ ○ ○ ○ ○	0,00
304	designo velour anti-slip mat with edging in nappa leather		○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with P62	* * * * *	
656	Centre console in high-gloss brown ash wood		○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 261/736/737/RVR	* * * * *	
		Not in conjunction with 728/732/738/764/779/H01/H05/H16/H32/H41/H64/H73	* * * * *	
		Not in conjunction with 736/H16/H41/H64/H73	* * * * *	
728	Centre console in black piano-lacquer look		○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 261/736/737/RVR	* * * * *	
		Not in conjunction with 656/732/738/764/779/H01/H05/H06/H32/H73	* * * * *	
		Not in conjunction with 736/H73	* * * * *	
732	AMG carbon-fibre centre console		● ● ● ● ● ●	997,50
		Not in conjunction with 261/736/737/RVR	* * * * *	
		Not in conjunction with 656/728/738/764/779/H01/H05/H06/H16/H32/H64	* * * * *	
		Not in conjunction with 736/H16/H64	* * * * *	
		Only in conjunction with 876+891	* * * * *	
		i.V.m. Code PYB	● ● ● ● ● ●	840,00
		i.V.m. Code H73	○ ○ ○ ○ ○ ○	0,00
737	Centre console in black open-pored ash wood		○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 11R/201A/204A/205A/208A/211A/301A/469/49R/55U/58U/601A/632/645/656/	* * * * *	
		Not in conjunction with H16/H64/H73	* * * * *	
		Only in conjunction with 275+P49	* * * * *	
		Only in conjunction with P29+P31+P35+P49	* * * * *	
738	Centre console in light brown open-pored elm wood		○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 261/736/737/RVR	* * * * *	
		Not in conjunction with 656/728/732/764/779/H01/H06/H16/H32/H41/H64/H73	* * * * *	
		Not in conjunction with 736/H16/H41/H64/H73	* * * * *	
764	Centre console in grey open-pore ash wood		○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 261/736/737/RVR	* * * * *	
		Not in conjunction with 656/728/732/738/779/H01/H05/H06/H16/H41/H64/H73	* * * * *	
		Not in conjunction with 736/H16/H41/H64/H73	* * * * *	
779	Centre console in high-gloss light brown sen wood		○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 261/736/737/RVR	* * * * *	
		Not in conjunction with 656/728/732/738/764/H05/H06/H16/H32/H41/H64/H73	* * * * *	
		Not in conjunction with 736/H16/H41/H64/H73	* * * * *	
H16	designo piano lacquer, black flowing lines		● ● ● ● ● ●	1.044,75
		Not in conjunction with 261/736/737/RVR	* * * * *	
		Not in conjunction with 656/732/738/764/779/H01/H05/H06/H32/H41/H64/H73	* * * * *	
		Not in conjunction with 656/736/738/779/H32/H41/H64/H73	* * * * *	
		Not in conjunction with 732/737	* * * * *	
		Only in conjunction with 728	* * * * *	
		i.V.m. Code P62/P87	● ● ● ● ● ●	834,75
		i.V.m. Code PYB	● ● ● ● ● ●	635,25
		i.V.m. Code(PYN/PYO)+(P62/P87)	● ● ● ● ● ●	425,25
PBP	ENERGIZING package		● ● ● ● ● -	939,75
		Includes codes 355+868+873 [401/902]+891	- - - - - ●	561,75
		Not in conjunction with 548/PBR	* * * * *	
		Only in conjunction with 549+P21	* * * * *	
		i.V.m. Code PYO	○ ○ ○ ○ ○ ○	0,00
PBR	ENERGIZING package Plus		● ● ● ● ● -	4.593,75
		Includes codes 355+401+432+868+891	- - - - - ●	4.215,75
		Not in conjunction with 301A/601A	* * * * *	
		Not in conjunction with 548/873/PBP	* * * * *	
		Not in conjunction with 671A	* * * * *	
		Only in conjunction with 275+549+P21+P49+P68	* * * * *	
		Only in conjunction with 436	* * * * *	
		i.V.m. Code PYO	● ● ● ● ● ●	3.654,00
B20	designo velour floor mats with edging in nappa leather		○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 58U/802A/809A/814A/824A/827A/828A/834A/B23/B62/P62/P89/PAQ/U04/U12/	* * * * *	

B62	designo high-pile floor mats with edging in nappa leath		● ● ● ● ● ● ●	546,00
		Not in conjunction with B20/P62/U04/U12/U26	* * * * *	
		i.V.m. Code P89/PAQ	○ ○ ○ ○ ○ -	0,00
U04	designo floor mats		○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 201A/204A/205A/208A/211A/261/301A/601A/736/737/801A/804A/805A/808A/809A/818A/871A/875A/877A/878A	* * * * *	
		Not in conjunction with 201A/204A/205A/208A/211A/301A/601A/801A/804A/805A/808A/887A/U12		
		Not in conjunction with 58U/U26	* * * * *	
		Not in conjunction with 671A/861A/871A/875A/877A/878A		
		Not in conjunction with B20/B23/B62/P89/PAQ/U12	* * * * *	
		Only in conjunction with [951A/955A]	* * * * *	
		Only in conjunction with [957A]	* * * * *	
U12	Velour floor mats		● ● ● ● ● ● -	99,75
		Not in conjunction with 032U/041U/049U/124U/385U/431/772/773U/825U/904U/947U/B20/B23/B62/U12	* * * * *	
		Not in conjunction with 211A/261/601A/736/737/772/887A/951A/955A/L5C/P29/P31/P62/P87/RVR/U04	* * * * *	
		Not in conjunction with 211A/601A/887A/951A/955A/L5C/P29/P31/P62/P87/U04/U26/U95		
		Not in conjunction with U29		
		Not in conjunction with U95	* * * *	
		Only in conjunction with 428+L3B+P14+P15	* * * * *	
		Only in conjunction with [201A/204A/205A/208A/301A/801A/804A/805A/808A/818A]	* * *	
		i.V.m. Code PYB	○ ○ ○ ○ ○ -	0,00
U26	AMG floor mats		○ ○ ○ ○ ○ ○	0,00
		Available only as part of [P29]	* * * *	
		Not in conjunction with 11R/301A/469/49R/83R/951A/955A/R70/R82/R98/U12		
		Not in conjunction with 11R/301A/469/49R/83R/R70/R82/R98/U12	* * * *	
		Not in conjunction with 301A/818A/957A/B20/B62/P14/P15/P62/P87/PAQ/U12	* * * * *	
		Not in conjunction with 951A/955A/P62/P87/U04	* * * *	
		Not in conjunction with 951A/955A/U04	* * * * *	
		Not in conjunction with P62/P87/U04		
		Not in conjunction with U29		
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	* * * * *	
		Only in conjunction with P29+P31	* * *	
		Only in conjunction with U95	* * *	
U45	AMG illuminated door sills with "AMG" lettering and w		- - - - - ●	178,50
		i.V.m. Code PYB	- - - - - ○	0,00
U45	Door sills with "Mercedes-Benz" lettering, illuminated		● ● ● ● ● -	178,50
		i.V.m. Code PYB	○ ○ ○ ○ ○ -	0,00
256	AMG Track Pace		- - - - - ●	262,50
		Not in conjunction with 548		*
		Only in conjunction with 365+549		*
		i.V.m. Code PYC	- - - - - ○	0,00
463	Head-up Display		● ● ● ● ● ●	1.039,50
868	Widescreen cockpit		● ● ● ● ● ●	787,50
		i.V.m. Code PYM/PYN/PYO	○ ○ ○ ○ ○ ○	0,00
U19	MBUX augmented reality for navigation		● ● ● ● ● ●	409,50
		Not in conjunction with 548	* * * * *	
		Only in conjunction with 365+549+868	* * * * *	
		i.V.m. Code PYN/PYO	○ ○ ○ ○ ○ ○	0,00
876	Interior Light package		S S S S S S	0,00
891	Ambient lighting		S S S S S S	0,00
51U	Roof liner in black fabric		● ● ● ● ● -	367,50
			- - - - - ○	0,00
		Not in conjunction with 204A/205A/804A/805A/818A/957A	* * * * *	
		Not in conjunction with 204A/205A/804A/805A/955A		
		Not in conjunction with 204A/205A/804A/805A	* * * *	
		Not in conjunction with 55U/58U/61U/65U/955A/P87	* * * * *	
		Not in conjunction with 55U/58U/61U/65U/P87		
		Not in conjunction with 875A		*
		i.V.m. Code P29/P62	○ ○ ○ ○ ○ -	0,00
55U	Roof liner in macchiato beige fabric		○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 201A/208A/211A/301A/601A/801A/808A/887A/951A		
		Not in conjunction with 208A/211A/261/301A/601A/736/737/808A/887A/RVR	* * * *	
		Not in conjunction with 51U/58U/61U/65U/951A/P62	* * * *	
		Not in conjunction with 51U/58U/61U/65U/P62	* * * * *	
		Not in conjunction with B23/P89	* * * * *	
		Not in conjunction with L6G/L6K/U17/Y05		*

		Only in conjunction with [204A/205A/804A/805A/818A/957A]	*	*	*	*	*	*		
		Only in conjunction with [875A]							*	
		Only in conjunction with [955A]	*	*	*	*	*	*	*	
58U	Roof liner in crystal grey fabric		○	○	○	○	○	○		0,00
		Not in conjunction with 204A/205A/211A/261/601A/736/737/804A/805A/887A/RVR	*							
		Not in conjunction with 204A/205A/211A/601A/804A/805A/887A/951A/955A	*							
		Not in conjunction with 51U/55U/61U/65U/951A/955A/P62/P87/U04	*							
		Not in conjunction with 51U/55U/61U/65U/P62/P87/U04								
		Not in conjunction with 51U/55U/61U/65U/U04	*	*	*	*	*	*	*	
		Not in conjunction with B20/B23/P62/P87/P89	*	*	*	*	*	*	*	
		Only in conjunction with U26							*	
		Only in conjunction with [201A/208A/301A/801A/808A]	*	*	*	*	*	*	*	
61U	designo roof lining in black DINAMICA microfibre		●	●	●	●	●	●	●	1.680,00
		Not in conjunction with 204A/205A/804A/805A/818A/957A	*	*	*	*	*	*	*	
		Not in conjunction with 204A/205A/804A/805A/955A								
		Not in conjunction with 204A/205A/804A/805A	*							
		Not in conjunction with 51U/55U/58U/65U/955A/P87	*	*	*	*	*	*	*	
		Not in conjunction with 51U/55U/58U/65U/P87								
		Not in conjunction with 875A							*	
		Only in conjunction with 414	*	*	*	*	*	*	*	
65U	designo roof liner in macchiato beige DINAMICA microfibre		●	●	●	●	●	●	●	1.680,00
		Not in conjunction with 201A/208A/211A/301A/601A/801A/808A/887A/951A								
		Not in conjunction with 208A/211A/261/301A/601A/736/737/808A/887A/RVR	*							
		Not in conjunction with 51U/55U/58U/61U/951A/P62	*							
		Not in conjunction with 51U/55U/58U/61U/P62	*	*	*	*	*	*	*	
		Not in conjunction with B23/P89	*	*	*	*	*	*	*	
		Only in conjunction with 414+[955A]	*	*	*	*	*	*	*	
		Only in conjunction with 414	*							
		Only in conjunction with [204A/205A/804A/805A/818A/957A]	*	*	*	*	*	*	*	
		Only in conjunction with [671A/875A]							*	
275	Memory package		●	●	●	●	●	●	●	1.071,00
		Only in conjunction with P49	*	*	*	*	*	*	*	
		i.V.m. Code PYO	○	○	○	○	○	○	○	0,00
401	Climatised front seats		●	●	●	●	●	●	—	1.155,00
			—	—	—	—	—	—	●	777,00
		Not in conjunction with 301A/601A	*	*	*	*	*	*	*	
		Not in conjunction with 671A							*	
		Not in conjunction with 873	*	*	*	*	*	*	*	
		Only in conjunction with 275+P49	*	*	*	*	*	*	*	
		i.V.m. Code P68/432	●	●	●	●	●	●	—	777,00
		i.V.m. Code PBP	●	●	●	●	●	●	—	777,00
		i.V.m. Code PYN/PYO	●	●	●	●	●	●	—	777,00
		i.V.m. Code PBR	○	○	○	○	○	○	○	0,00
432	Active Multicontour Seat package		●	●	●	●	●	●	●	2.047,50
		Not in conjunction with 301A	*	*	*	*	*	*	*	
		Not in conjunction with 873	*	*	*	*	*	*	*	
		Only in conjunction with 275+902+P49	*	*	*	*	*	*	*	
		Only in conjunction with 436	*	*	*	*	*	*	*	
		i.V.m. Code PBP	●	●	●	●	●	●	●	1.669,50
		i.V.m. Code PYN/PYO	●	●	●	●	●	●	●	1.669,50
		i.V.m. Code PBR	○	○	○	○	○	○	○	0,00
436	Comfort front head restraints		○	○	○	○	○	○	—	0,00
		Not in conjunction with 301A/873	*	*	*	*	*	*	*	
		Only in conjunction with 275+432+902+P49	*	*	*	*	*	*	*	
873	Heated front seats		●	●	●	●	●	●	—	378,00
			—	—	—	—	—	—	S	0,00
		Not in conjunction with 401/432/902/906/P68	*							
		Not in conjunction with 401/432/902/P68/PBR	*	*	*	*	*	*	*	
		Not in conjunction with 401/432/902/P68								
		Not in conjunction with 436	*	*	*	*	*	*	*	
		i.V.m. Code PBP	○	○	○	○	○	○	—	0,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	—	0,00
902	Seat heating Plus for driver and front passenger seats		○	○	○	○	○	○	○	0,00
		Not in conjunction with 301A	*	*	*	*	*	*	*	
		Not in conjunction with 873	*	*	*	*	*	*	*	

872	Heated rear seats		● ● ● ● ● ● ●	378,00
		Not in conjunction with 301A	* * * * *	
418	designo two-tone steering wheel in nappa leather		● ● ● ● ● ● ●	1.029,00
		Not in conjunction with 431/B23/L5C/P62	* * * * *	
		Only in conjunction with 275+428+443+L3B+P49	* * * * *	
		i.V.m. Code P89	○ ○ ○ ○ ○ ●	0,00
431	Galvanised steering-wheel gearshift paddles		○ ○ ○ ○ ○ S	0,00
		Not in conjunction with 301A/418/428/443/802A/807A/809A/814A/818A/824A/827A/828A/834A/L3B/P62	* * * * *	
		Not in conjunction with 428/443/L3B/P87	*	
446	Touchpad without Controller		S S S S S S	0,00
		Not in conjunction with 448	* * * * *	
448	Touchpad with Controller		● ● ● ● ● ● ●	63,00
		Not in conjunction with 446/77B	* * * * *	
77B	MBUX Interior Assistant		● ● ● ● ● ● ●	315,00
		Not in conjunction with 448/811	* * * * *	
		Only in conjunction with 446+B18	* * * * *	
B23	Omission of two-tone steering wheel		○ ○ ○ ○ ○ ●	0,00
		Not in conjunction with 418/55U/58U/65U/B20/P14/P15/P62/P87/U04/U12	* * * * *	
		Only in conjunction with [802A/809A/814A/824A/827A/828A/834A/RRE/RRF/RVO/RVP/RVR]	* * * * *	
L3B	Multifunction sports steering wheel in nappa leather		S S S S S ●	0,00
		Not in conjunction with 431/L5C	* * * * *	
		Only in conjunction with 428	* * * * *	
L5C	Multifunction sports steering wheel in nappa leather		○ ○ ○ ○ ○ ●	0,00
		Not in conjunction with 301A/418/428/443/802A/807A/809A/814A/818A/824A/827A/828A/834A/L3B/P62	* * * * *	
		Not in conjunction with 301A/428/443/L3B/P87/U12	*	
		Only in conjunction with 431	* * * * *	
U88	AMG steering wheel buttons		- - - - - ●	367,50
		Not in conjunction with 443		*
301	Ashtray inserts with cigarette lighter in the front and rear		● ● ● ● ● ● ●	47,25
309	Double cup holder		○ ○ ○ ○ ○ ○ ○	0,00
		Available only as part of (30P)	* * * * *	
		Only in conjunction with 30P	* * * * *	
30P	Stowage Space package		● ● ● ● ● ● ●	63,00
		Includes codes 309	* * * * *	
		i.V.m. Code PYB	○ ○ ○ ○ ○ ○ ○	0,00
B18	Spectacles compartment for driver		○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 811	* * * * *	
736	Open-pore black ash wood trim		● ● ● ● ● ● ●	409,50
		Not in conjunction with 11R/201A/204A/205A/208A/211A/301A/469/49R/55U/58U/601A/632/645/656/657/658/659/660/661/662/663/664/665/666/667/668/669/670/671/672/673/674/675/676/677/678/679/680/681/682/683/684/685/686/687/688/689/690/691/692/693/694/695/696/697/698/699/700/701/702/703/704/705/706/707/708/709/710/711/712/713/714/715/716/717/718/719/720/721/722/723/724/725/726/727/728/729/730/731/732/733/734/735/736/737/738/739/740/741/742/743/744/745/746/747/748/749/750/751/752/753/754/755/756/757/758/759/760/761/762/763/764/765/766/767/768/769/770/771/772/773/774/775/776/777/778/779/780/781/782/783/784/785/786/787/788/789/790/791/792/793/794/795/796/797/798/799/800/801/802/803/804/805/806/807/808/809/810/811/812/813/814/815/816/817/818/819/820/821/822/823/824/825/826/827/828/829/830/831/832/833/834/835/836/837/838/839/840/841/842/843/844/845/846/847/848/849/850/851/852/853/854/855/856/857/858/859/860/861/862/863/864/865/866/867/868/869/870/871/872/873/874/875/876/877/878/879/880/881/882/883/884/885/886/887/888/889/890/891/892/893/894/895/896/897/898/899/900/901/902/903/904/905/906/907/908/909/910/911/912/913/914/915/916/917/918/919/920/921/922/923/924/925/926/927/928/929/930/931/932/933/934/935/936/937/938/939/940/941/942/943/944/945/946/947/948/949/950/951/952/953/954/955/956/957/958/959/960/961/962/963/964/965/966/967/968/969/970/971/972/973/974/975/976/977/978/979/980/981/982/983/984/985/986/987/988/989/990/991/992/993/994/995/996/997/998/999/1000	*	
		Not in conjunction with 656/738/779/957A/H16/H32/H41/H64/H73	* * * * *	
		Not in conjunction with 728/732		*
		Not in conjunction with 955A/P87	* * * * *	
		Only in conjunction with 275+737+P49	* * * * *	
		Only in conjunction with P29+P31+P35+P49	*	
		i.V.m. Code P62	● ● ● ● ● ● ●	199,50
		i.V.m. Code PYB	● ● ● ● ● ● ●	52,50
H01	High-gloss light brown sen wood trim		● ● ● ● ● ● ●	409,50
		Not in conjunction with 261/736/737/RVR	*	
		Not in conjunction with 656/728/732/738/764/H05/H06/H16/H32/H41/H64/H73	*	
		Not in conjunction with 736/H16/H41/H64/H73	* * * * *	
		Only in conjunction with 779	* * * * *	
		i.V.m. Code P62/P87	● ● ● ● ● ● ●	199,50
		i.V.m. Code PYB	● ● ● ● ● ● ●	52,50
H05	Open-pore light brown elm wood trim		● ● ● ● ● ● ●	409,50
		Not in conjunction with 261/736/737/RVR	*	
		Not in conjunction with 656/728/732/764/779/H01/H06/H16/H32/H41/H64/H73	*	
		Not in conjunction with 736/H16/H41/H64/H73	* * * * *	
		Only in conjunction with 738	* * * * *	
		i.V.m. Code P62	● ● ● ● ● ● ●	199,50
		i.V.m. Code PYB	● ● ● ● ● ● ●	52,50
		i.V.m. Code P87	○ ○ ○ ○ ○ ○ ○	0,00
H06	brown high-gloss ash wood trim		● ● ● ● ● ● ●	409,50
		Not in conjunction with 261/736/737/RVR	*	
		Not in conjunction with 728/732/738/764/779/H01/H05/H16/H32/H41/H64/H73	*	
		Not in conjunction with 736/H16/H41/H64/H73	* * * * *	

		Only in conjunction with 656	*	*	*	*	*	*	
		i.V.m. Code P62/P87	●	●	●	●	●	●	199,50
		i.V.m. Code PYB	●	●	●	●	●	●	52,50
H32	Grey open-pore ash wood trim		●	●	●	●	●	●	409,50
		Not in conjunction with 261/736/737/RVR	*						
		Not in conjunction with 656/728/732/738/779/H01/H05/H06/H16/H41/H64/H73	*						
		Not in conjunction with 736/H16/H41/H64/H73	*	*	*	*	*	*	
		Only in conjunction with 764	*	*	*	*	*	*	
		i.V.m. Code P87	●	●	●	●	●	●	199,50
		i.V.m. Code P62	○	○	○	○	○	○	0,00
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
H41	Light longitudinal-grain aluminium trim		○	○	○	○	○	○	0,00
		Not in conjunction with 261/736/737/RVR	*						
		Not in conjunction with 656/736/738/779/H16/H32/H64/H73	*	*	*	*	*	*	
		Not in conjunction with 656/738/764/779/H01/H05/H06/H16/H32/H64/H73	*						
		Only in conjunction with [728/732/737]	*	*	*	*	*	*	
H64	Metal-weave trim		●	●	●	●	●	●	472,50
		Not in conjunction with 261/736/737/RVR	*						
		Not in conjunction with 656/732/738/764/779/H01/H05/H06/H16/H32/H41/H73	*						
		Not in conjunction with 656/736/738/779/H16/H32/H41/H73	*	*	*	*	*	*	
		Not in conjunction with 732/737						*	
		Only in conjunction with 728	*	*	*	*	*	*	
		i.V.m. Code P62/P87	●	●	●	●	●	●	262,50
		i.V.m. Code PYB	●	●	●	●	●	●	63,00
H73	AMG carbon-fibre trim		●	●	●	●	●	●	3.097,50
		Not in conjunction with 261/736/737/RVR	*						
		Not in conjunction with 656/728/738/764/779/H01/H05/H06/H16/H32/H41/H64	*						
		Not in conjunction with 656/736/738/779/H16/H32/H41/H64	*	*	*	*	*	*	
		Not in conjunction with 728/737						*	
		Only in conjunction with 732+876+891							
		Only in conjunction with 732	*	*	*	*	*	*	
		i.V.m. Code PYB	●	●	●	●	●	●	2.688,00
861A	black		-	-	-	-	-	●	2.310,00
		Not in conjunction with 55U/58U/65U/U04						*	
		Only in conjunction with 275+287+P49+U26						*	
		i.V.m. Code PYM/PYN/PYO	-	-	-	-	-	○	0,00
871A	black		-	-	-	-	-	●	2.310,00
		Not in conjunction with 55U/65U/U04						*	
		Only in conjunction with 275+287+P49+U26						*	
		i.V.m. Code PYM/PYN/PYO	-	-	-	-	-	○	0,00
875A	macchiato beige / magma grey		-	-	-	-	-	●	2.520,00
		Not in conjunction with 51U/58U/61U/L6G/L6K/U04						*	
		Only in conjunction with 275+287+P49+U26						*	
		i.V.m. Code PYM/PYN/PYO	-	-	-	-	-	○	0,00
877A	bengal red / black		-	-	-	-	-	●	2.520,00
		Not in conjunction with 55U/58U/65U/U04						*	
		Only in conjunction with 275+287+P49+U26						*	
		i.V.m. Code PYM/PYN/PYO	-	-	-	-	-	○	0,00
878A	magma grey / espresso brown		-	-	-	-	-	●	2.520,00
		Not in conjunction with 55U/58U/65U/L6G/U04						*	
		Only in conjunction with 275+287+P49+U26						*	
		i.V.m. Code PYM/PYN/PYO	-	-	-	-	-	○	0,00
601A	black		○	○	○	○	○	-	0,00
		Available only as part of [P29]	*		*	*	*	*	
		Not in conjunction with 11R/301A/401/469/49R/55U/58U/65U/83R/951A/955A/P62/P87/R70/R82/R98/U04/U12/U38	*	*	*	*	*	*	
		Not in conjunction with 401/55U/58U/65U/B23/P14/P15/P62/P87/P89/PBR/U04/U12/U38	*	*	*	*	*	*	
		Not in conjunction with U29							
		Only in conjunction with P29+P31+U26							
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with U95		*	*	*	*	*	
671A	black		-	-	-	-	-	○	0,00
		Not in conjunction with 401/55U/PBR/U04/U38						*	
		Only in conjunction with U26						*	
301A	black		○	○	○	○	○	-	0,00
		Not in conjunction with 032U/041U/049U/124U/385U/401/431/432/436/55U/65U/772/773U/825U/872	*	*	*	*	*	*	

		Not in conjunction with U29			*	*	*	*		
		Not in conjunction with U95			*	*	*	*		
		Only in conjunction with 428+L3B+P14+P15		*	*	*	*	*		
802A	yacht blue / black		○	○	○	○	○	-		0,00
		Not in conjunction with 431/55U/58U/65U/B20/L5C/P14/P15/P62/P87/PAQ/U04/U12		*	*	*	*	*		
		Only in conjunction with 275+287+428+L3B+P29+P31+P49+P89+[RRE/RRF/RVO/RVP/RVR]		*	*	*	*	*		
		Only in conjunction with U95			*	*	*	*		
809A	deep white / black		○	○	○	○	○	-		0,00
		Not in conjunction with 431/55U/58U/65U/B20/L5C/P14/P15/P62/P87/PAQ/U04/U12		*	*	*	*	*		
		Only in conjunction with 275+287+428+L3B+P29+P31+P49+P89+[RRE/RRF/RVO/RVP/RVR]		*	*	*	*	*		
		Only in conjunction with U95			*	*	*	*		
814A	armagnac brown / black		○	○	○	○	○	-		0,00
		Not in conjunction with 431/55U/58U/65U/B20/L5C/P14/P15/P62/P87/PAQ/U04/U12		*	*	*	*	*		
		Only in conjunction with 275+287+428+L3B+P29+P31+P49+P89+[RRE/RRF/RVO/RVP/RVR]		*	*	*	*	*		
		Only in conjunction with U95			*	*	*	*		
824A	truffle brown / black		○	○	○	○	○	-		0,00
		Not in conjunction with 431/55U/58U/65U/B20/L5C/P14/P15/P62/P87/PAQ/U04/U12		*	*	*	*	*		
		Only in conjunction with 275+287+428+L3B+P29+P31+P49+P89+[RRE/RRF/RVO/RVP/RVR]		*	*	*	*	*		
		Only in conjunction with U95			*	*	*	*		
827A	classic red / black		○	○	○	○	○	-		0,00
		Not in conjunction with 431/55U/58U/65U/B20/L5C/P14/P15/P62/P87/PAQ/U04/U12		*	*	*	*	*		
		Only in conjunction with 275+287+428+L3B+P29+P31+P49+P89+[RRE/RRF/RVO/RVP/RVR]		*	*	*	*	*		
		Only in conjunction with U95			*	*	*	*		
828A	crystal grey / black		○	○	○	○	○	-		0,00
		Available only as part of (P89)		*	*	*	*	*		
		Not in conjunction with 431/55U/58U/65U/B20/L5C/P14/P15/P62/P87/PAQ/U04/U12		*	*	*	*	*		
		Only in conjunction with 275+287+428+L3B+P29+P31+P49+P89+[RRE/RRF/RVO/RVP/RVR]		*	*	*	*	*		
		Only in conjunction with U95			*	*	*	*		
834A	saddle brown / black		○	○	○	○	○	-		0,00
		Not in conjunction with 431/55U/58U/65U/B20/L5C/P14/P15/P62/P87/PAQ/U04/U12		*	*	*	*	*		
		Only in conjunction with 275+287+428+L3B+P29+P31+P49+P89+[RRE/RRF/RVO/RVP/RVR]		*	*	*	*	*		
		Only in conjunction with U95			*	*	*	*		
957A	tizian red / macchiato beige		●	●	●	●	●	-		1.890,00
		Not in conjunction with 51U/58U/61U/736/B23/P62/P89/U12/U26		*	*	*	*	*		
807A	Bengal red / black		●	●	●	●	●	-		4.200,00
		Not in conjunction with 431/55U/58U/65U/B23/L5C/P14/P15/P62/P87/P89/U04/U12		*	*	*	*	*		
		Only in conjunction with 275+287+428+L3B+P29+P31+P49+[RRE/RRF/RVO/RVP/RVR]		*	*	*	*	*		
		Only in conjunction with U95			*	*	*	*		
		i.V.m. Code PYN/PYO		●	-	●	●	●	-	2.646,00
818A	magma grey / macchiato beige		●	●	●	●	●	-		4.347,00
		Not in conjunction with 032U/041U/049U/124U/385U/431/51U/58U/61U/772/773U/825U/904U/947U/E		*	*	*	*	*		
		Not in conjunction with U29			*	*	*	*		
		Not in conjunction with U95		*	*	*	*	*		
		Only in conjunction with 428+L3B+P14+P15		*	*	*	*	*		
		i.V.m. Code PYM/PYN/PYO		●	-	●	●	●	-	2.530,50
951A	black / titanium grey pearl		○	○	○	○	○	○		0,00
		Available only as part of (P62)						*		
		Not in conjunction with 211A/301A/601A/887A/U12								
		Not in conjunction with 55U/58U/65U/P87/U26								
		Not in conjunction with 55U/58U/65U/U26		*	*	*	*	*	*	
		Not in conjunction with B23/P87/P89/U12		*	*	*	*	*		
		Not in conjunction with U17/Y05						*		
		Only in conjunction with 275+287 +P49+P62						*		
955A	macchiato beige / tizian red		○	○	○	○	○	○		0,00
		Available only as part of (P87)						*		
		Not in conjunction with 211A/301A/601A/887A/U12								
		Not in conjunction with 51U/58U/61U/736/U26		*	*	*	*	*	*	
		Not in conjunction with 51U/58U/61U/P62/U26								
		Not in conjunction with B23/P62/P89/U12		*	*	*	*	*		
		Not in conjunction with L6G/L6K/U17/Y05						*		
		Only in conjunction with 275+287 +P49+P87						*		
201A	black		●	●	●	●	●	-		1.816,50
		Not in conjunction with 55U/65U/B23/P62/P87/P89/U04/U38		*	*	*	*	*		
		Not in conjunction with 55U/65U/P62/P87/U04/U38								
		i.V.m. Code P31		●	●	●	●	●	-	1.554,00

		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	–	0,00
204A	marsala brown / espresso brown		●	●	●	●	●	●	–	2.026,50
		Not in conjunction with 51U/58U/61U/B23/P62/P87/P89/U04/U38	*	*	*	*	*	*		
		Not in conjunction with 51U/58U/61U/P62/P87/U04/U38								
		i.V.m. Code P31	●	●	●	●	●	●	–	1.764,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	–	0,00
205A	macchiato beige / magma grey		●	●	●	●	●	●	–	2.026,50
		Not in conjunction with 51U/58U/61U/B23/P62/P87/P89/U04/U38	*	*	*	*	*	*		
		i.V.m. Code P31	●	●	●	●	●	●	–	1.764,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	–	0,00
208A	magma grey / espresso brown		●	●	●	●	●	●	–	2.026,50
		Not in conjunction with 55U/65U/B23/P62/P87/P89/U04/U38	*	*	*	*	*	*		
		Not in conjunction with 55U/65U/P62/P87/U04/U38								
		i.V.m. Code P31	●	●	●	●	●	●	–	1.764,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	–	0,00
211A	black		●	●	●	●	●	●	–	1.554,00
		Not in conjunction with 55U/58U/65U/B23/P14/P15/P62/P87/P89/U04/U12/U38	*	*	*	*	*	*		
		Only in conjunction with 287+P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*		
		Only in conjunction with U95		*	*	*	*	*		
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	–	0,00
801A	black		●	●	●	●	●	●	–	3.087,00
		Not in conjunction with 55U/65U/B23/P62/P87/P89/U04	*	*	*	*	*	*		
		Not in conjunction with 55U/65U/P62/P87/U04								
		i.V.m. Code P31	●	●	●	●	●	●	–	2.310,00
		i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	–	1.270,50
		i.V.m. Code PYH+(PYM/PYN/PYO)	●	●	●	●	●	●	–	756,00
804A	marsala brown / espresso brown		●	●	●	●	●	●	–	3.297,00
		Not in conjunction with 51U/58U/61U/B23/P62/P87/P89/U04	*	*	*	*	*	*		
		Not in conjunction with 51U/58U/61U/P62/P87/U04								
		i.V.m. Code P31	●	●	●	●	●	●	–	2.520,00
		i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	–	1.270,50
		i.V.m. Code PYH+(PYM/PYN/PYO)	●	●	●	●	●	●	–	756,00
805A	macchiato beige / magma grey		●	●	●	●	●	●	–	3.297,00
		Not in conjunction with 51U/58U/61U/B23/P62/P87/P89/U04	*	*	*	*	*	*		
		Not in conjunction with 51U/58U/61U/P62/P87/U04								
		i.V.m. Code P31	●	●	●	●	●	●	–	2.520,00
		i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	–	1.270,50
		i.V.m. Code PYH+(PYM/PYN/PYO)	●	●	●	●	●	●	–	756,00
808A	magma grey / espresso brown		●	●	●	●	●	●	–	3.297,00
		Not in conjunction with 55U/65U/B23/P62/P87/P89/U04	*	*	*	*	*	*		
		Not in conjunction with 55U/65U/P62/P87/U04								
		i.V.m. Code P31	●	●	●	●	●	●	–	2.520,00
		i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	–	1.270,50
		i.V.m. Code PYH+(PYM/PYN/PYO)	●	●	●	●	●	●	–	756,00
887A	black / bengal red		●	●	●	●	●	●	–	2.520,00
		Not in conjunction with 11R/301A/469/49R/55U/58U/65U/83R/951A/955A/P62/P87/R70/R82/R98/U04/U12								
		Not in conjunction with 55U/58U/65U/B23/P14/P15/P62/P87/P89/U04/U12	*	*	*	*	*	*		
		Not in conjunction with U29								
		Only in conjunction with 287+P29+P31+U26								
		Only in conjunction with 287+P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*		
		Only in conjunction with U95		*	*	*	*	*		
		i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	–	756,00
P14	AVANTGARDE interior		S	S	S	S	S	S	–	0,00
		Includes codes 51U [55U/58U/61U/65U]+H01 [736/H05/H06/H16/H32/H41/H64/H73]+L3B [L5C]	*	*	*	*	*	*		
		Not in conjunction with 032U/041U/049U/124U/211A/385U/601A/772/773U/802A/807A/809A/814A/824	*	*	*	*	*	*		
		Not in conjunction with U29			*	*	*	*		
		Not in conjunction with U95		*	*	*	*	*		
		Only in conjunction with P15	*	*	*	*	*	*		
P15	AVANTGARDE exterior		S	S	S	S	S	S	–	0,00
		Includes codes 83R [11R/49R/R70/R82/R98/RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*		
		Not in conjunction with 032U/041U/049U/124U/211A/385U/601A/772/773U/802A/807A/809A/814A/824	*	*	*	*	*	*		
		Not in conjunction with U29			*	*	*	*		
		Not in conjunction with U95		*	*	*	*	*		
		Only in conjunction with P14	*	*	*	*	*	*		
P29	AMG Line interior		○	○	○	○	○	○	–	0,00

		Includes codes 601A [201A/204A/205A/208A/211A/801A/804A/805A/808A/887A/951A/955A]+H41 [H16/	*		*	*	*	*		
		Not in conjunction with 11R/301A/469/49R/83R/R70/R8Z/R98/U12	*							
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*		
		Not in conjunction with U29								
		Only in conjunction with P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*		
		Only in conjunction with P31	*							
		Only in conjunction with U95		*	*			*		
P31	AMG Line exterior		●	●	●	●	●	●	-	2.887,50
		Includes codes 772+RRE [RRF/RVO/RVP]	*		*	*	*	*		
		Includes codes 772		*						
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*		
		Only in conjunction with P29+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*		
		Only in conjunction with U95		*	*	*	*	*		
		i.V.m. Code U95	●	●	●	●	●	●	-	3.097,50
		i.V.m. Code PYH	○	○	○	○	○	○	-	0,00
362	Communications module (LTE) for the use of Mercedes		○	○	○	○	○	○		0,00
20U	Pre-installation for car sharing		●	●	●	●	●	●		52,50
		i.V.m. Code PYB	○	○	○	○	○	○		0,00
33U	Remote Services Plus		●	●	●	●	●	●		157,50
		Not in conjunction with 34U	*	*	*	*	*	*		
		i.V.m. Code PYB	○	○	○	○	○	○		0,00
34U	Remote Services Premium		●	●	●	●	●	●		262,50
		Not in conjunction with 33U	*	*	*	*	*	*		
351	Mercedes-Benz emergency call system		○	○	○	○	○	○		0,00
37U	Advanced connectivity Plus		●	●	●	●	●	●		262,50
000U	paintwork not yet finalised		○	○	○	○	○	○		0,00
		Only in conjunction with 524	*	*	*	*	*	*		
00B	Owner's Manual and service information - Danish		○	○	○	○	○	○		0,00
		Not in conjunction with 01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
01B	Owner's Manual and service information - Dutch		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
02B	Owner's Manual and service information - German		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
03B	Owner's Manual and service information - Russian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
04B	Owner's Manual and service information - Finnish		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
05B	Owner's Manual and service information - English		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
06B	Owner's Manual and service information - Italian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
07B	Owner's Manual and service information - French		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
08B	Owner's Manual and service information - Spanish		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
09B	Owner's Manual and service information - Portuguese		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/10B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
10B	Owner's Manual and service information - Swedish		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/11B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
11B	Owner's Manual and service information - Arabic		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/13B/14B/15B/16B/17B/30B/	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
12B	Owner's Manual and service information - English USA		-	-	-	-	○	○		0,00
12U	Preinstallation for Concierge Service		○	○	○	○	○	○		0,00

13B	Owner's Manual and service information - Norwegian		○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/14B/15B/16B/17B/30B	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
14B	Owner's Manual and service information - Greek		○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/15B/16B/17B/30B	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
15B	Owner's Manual and service information - Turkish		○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/16B/17B/30B	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/16B/17B/30B/31B/32B/33B/34B/35B/36B/								
15U	Pre-installation for Mercedes-Benz Link		○	○	○	○	○	○	○	0,00
16B	Owner's Manual and service information - Polish		○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/17B/30B	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/17B/30B/31B/32B/33B/34B/35B/36B/								
16U	Apple CarPlay		○	○	○	○	○	○	○	0,00
		Only in conjunction with 14U+17U	*	*	*	*	*	*	*	
17B	Owner's Manual and service information - Czech		○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/30B	*	*	*	*	*	*	*	
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/30B/31B/32B/33B/34B/35B/36B/								
17U	Android Auto		○	○	○	○	○	○	○	0,00
		Only in conjunction with 14U+16U	*	*	*	*	*	*	*	
18B	Owner's Manual and service information - English South Africa		○	○	○	○	○	○	○	0,00
18U	Baidu Carlife		-	-	-	-	-	-	-	0,00
19B	Owner's Manual and service information - French South Africa		○	○	○	○	○	○	○	0,00
20B	Owner's Manual and service information - Spanish South Africa		○	○	○	○	○	○	○	0,00
21B	Owner's Manual and service information - Portuguese South Africa		○	○	○	○	○	○	○	0,00
221	Electrically adjustable front seat, left		●	-	-	-	-	-	-	446,25
			-	-	-	-	○	○	○	0,00
222	Electrically adjustable front seat, right		●	-	-	-	-	-	-	446,25
			-	-	-	-	○	○	○	0,00
22B	Owner's Manual and service information - Japanese		○	-	-	-	○	○	○	0,00
232	Garage door opener (frequency range 284-390 MHz)		-	-	-	●	●	●	●	236,25
233	Active Distance Assist DISTRONIC		○	○	○	○	○	○	○	0,00
		Not in conjunction with 234/239/243/258								
		Not in conjunction with 234/243/504	*	*	*	*	*	*	*	
		Not in conjunction with 239					*			
		Not in conjunction with 258					*	*		
		Only in conjunction with 274+P49								
		Only in conjunction with 365+513+546+K34+P49	*	*	*	*	*	*	*	
239	Active Distance Assist DISTRONIC		●	●	●	●	●	●	●	630,00
		Not in conjunction with 233/23P/258/266/292/546/K32/K33/K34/P20	*							
		Not in conjunction with 233/23P/258/266/546/K32/K33/K34/P20								
		Not in conjunction with 233/546/K34					*			
		Not in conjunction with 23U/K33	*	*	*	*	*	*	*	
		Only in conjunction with 243	*	*	*	*	*	*	*	
23B	Owner's Manual and service information - simplified Chinese		-	-	-	○	-	-	-	0,00
23U	Active traffic-assist		○	○	○	○	○	○	○	0,00
		Not in conjunction with 234/243/504	*	*	*	*	*	*	*	
		Not in conjunction with 258						*		
		Only in conjunction with 235+365+513+546+K33+K34+P20+P49	*	*	*	*	*	*	*	
24B	Owner's Manual and service information - traditional Chinese		○	○	○	○	○	○	○	0,00
251	Increase in top speed, USA		-	-	-	-	-	●	●	2.310,00
25B	Owner's Manual and service information - Korean		-	○	○	-	○	○	○	0,00
261	Omission of emblem on front wing		-	-	-	-	-	○	○	0,00
263	Number plate mounting for Asia / Mexico		○	○	○	○	○	○	○	0,00
264	Number plate mounting for America		-	-	-	-	○	○	○	0,00
26B	Owner's Manual and service information - Chinese Taiwan		○	○	○	○	○	○	○	0,00
270	Aerial for GPS		S	S	S	S	S	S	S	0,00
274	Telephone aerial		○	○	○	○	○	○	○	0,00
		Not in conjunction with 897	*	*	*	*	*	*	*	
		Only in conjunction with 899	*	*	*	*	*	*	*	
27B	Fully electric front seats		-	-	-	-	●	●	●	892,50
			○	-	-	-	-	-	-	0,00
27B	Owner's Manual and Service Booklet - Spanish Mexico		○	○	○	○	○	○	○	0,00
2R4	Complete winter (M+S) wheel-and-tyre assembly x 4		●	●	●	●	●	●	-	2.205,00
		Not in conjunction with 4R6/645	*							

		only available with MQ-tyres	*	*	*	*	*	*		
30B	Owner's Manual and service information - Slovenian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/	*	*	*	*	*	*		
31B	Owner's Manual and service information - Hungarian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/	*	*	*	*	*	*		
32B	Owner's Manual and service information - Bulgarian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/	*	*	*	*	*	*		
33B	Owner's Manual and service information - Romanian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/	*	*	*	*	*	*		
34B	Owner's Manual and service information - Croatian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/36B/	*	*	*	*	*	*		
35B	Owner's Manual and service information - Latvian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/36B/	*	*	*	*	*	*		
36B	Owner's Manual and service information - Lithuanian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/	*	*	*	*	*	*		
37B	Owner's Manual and service information - Slovak		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/	*	*	*	*	*	*		
380	Car telephony		-	-	-	-	-	●		619,50
		Only in conjunction with 274						*		
38B	Owner's Manual and service information - Estonian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/	*	*	*	*	*	*		
39B	Owner's Manual and service information - Serbian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/	*	*	*	*	*	*		
40B	Owner's Manual and service information - Ukrainian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34B/35B/	*	*	*	*	*	*		
41B	Owner's Manual and service information - Hebrew		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
428	Steering wheel shift paddles		S	S	S	S	S	-		0,00
		Not in conjunction with 431/L5C	*	*	*	*	*			
42B	Owner's Manual and service information - Indonesian		○	○	○	○	○	○		0,00
43B	Owner's Manual and service information - Thai		○	○	○	○	○	○		0,00
44B	Owner's Manual and service information - Vietnamese		○	○	○	○	○	○		0,00
460	Canada specification		-	-	-	-	○	○		0,00
461	Instrument display in miles with English lettering		○	○	○	○	○	○		0,00
469	Increased tyre pressure		○	○	○	○	○	-		0,00
477	Tyre pressure loss warning system		○	○	○	○	○	○		0,00
494	USA specification		-	-	-	-	○	○		0,00
498	Japan specification		○	-	-	-	○	○		0,00
4R6	complete winter (M+S) wheel-and-tyre assembly x 4		●	●	●	●	●	-		2.919,00
		Not in conjunction with 2R4/645		*						
		only available with MOE-tyres	*	*	*	*	*	*		
501	360° camera		○	○	○	○	○	○		0,00
		Available only as part of (P47)	*	*	*	*	*	*		
		Not in conjunction with 218/P44	*	*	*	*	*	*		
		Only in conjunction with 274+P47+P49	*							
		Only in conjunction with P47+P49	*	*	*	*	*	*		
517	HD digital radio standard		○	○	○	○	○	○		0,00
524	Transport protection (full body cover)		●	●	●	●	●	●		168,00
536	Sirius satellite radio		-	-	-	-	●	●		708,75
548	CONNECT 20 MID (NTG6)		○	○	○	○	○	○		0,00
		Not in conjunction with 256		*				*		
		Not in conjunction with 549/865/PBP/PBR/U19	*	*	*	*	*	*		
549	MBUX multimedia system		○	○	○	○	○	○		0,00
		Not in conjunction with 548	*	*	*	*	*	*		

551	Anti-theft alarm system (ATA) with tow-away protection		○	○	○	○	○	○	0,00
552	Anti-theft alarm system with preinstallation for collision		○	○	○	○	○	○	0,00
598	Petrol particulate filter		-	-	-	○	-	-	0,00
59U	Roof liner in yellow /white fabric		○	○	○	○	○	-	0,00
608	Adaptive Highbeam Assist		●	●	●	●	●	●	189,00
		Not in conjunction with 628/642/P35	*	*	*	*	*	*	
		Only in conjunction with 632	*	*	*	*	*	*	
		i.V.m. Code P35	-	-	-	-	-	-	0,00
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
623	Gulf States specification		-	-	-	○	○	○	0,00
625	Australia specification		○	-	-	○	○	○	0,00
631	LED High Performance headlamps		○	○	○	○	○	○	0,00
634	Omission of first-aid kit		○	○	○	○	○	○	0,00
636	Omission of warning triangle		○	○	○	○	○	○	0,00
640	LED Intelligent Light System (LHD)		-	-	-	-	○	○	0,00
641	MULTIBEAM LED		○	○	○	○	○	○	0,00
642	MULTIBEAM LED		○	○	○	○	○	○	0,00
		Available only as part of (P35)	*	*	*	*	*	*	
		Not in conjunction with 608/632	*	*	*	*	*	*	
		Not in conjunction with 632	*						
		Only in conjunction with P35	*	*	*	*	*	*	
645	M+S winter tyres, set of 4		●	●	●	●	●	-	204,75
		Not in conjunction with 2R4/4R6/651/652		*					
		Not in conjunction with 469/49R/R01/R03/R06/R70/R82/R98/RVO/RVP/RVR							
		Not in conjunction with R01/R03/R06	*	*	*	*	*	*	
		Only in conjunction with [11R/83R/RRE/RRF]	*	*	*	*	*	*	
651	Winter complete wheels fitted		○	○	○	○	○	○	0,00
		Not in conjunction with 645/652		*					
652	Summer complete tyres fitted		○	○	○	○	○	○	0,00
		Not in conjunction with 645/651		*					
666	Freight packaging without tie-down hooks		●	●	●	●	●	●	0,00
668	Prod. prot. f. freight pkging with tie-down hooks		●	●	●	●	●	●	26,25
670	Residual engine heat utilisation		○	○	○	○	○	○	0,00
		Not in conjunction with 580	*	*	*	*	*	*	
		Only in conjunction with 581	*	*	*	*	*	*	
687	Type plate with model year		○	○	○	○	○	○	0,00
		Not in conjunction with 966/967	*	*	*	*	*	*	
690	Pre-installation for the spare wheel		○	○	○	○	○	○	0,00
6U7	BlueTEC diesel emission control system including generator		○	○	-	-	-	-	0,00
		Not in conjunction with U79		*					
		Only in conjunction with U85		*					
712	CKD delivery scope India		○	-	-	-	-	○	0,00
762	Remote control unit		○	○	○	○	○	○	0,00
763	Key with Radio remote control with panic switch		-	-	-	○	○	○	0,00
772	AMG bodystyling		●	●	●	●	●	●	997,50
		Available only as part of (P31)	*	*	*	*	*	*	
		Not in conjunction with 11R/301A/469/49R/83R/R70/R82/R98/U12	*						
		Not in conjunction with 301A/818A/P14/P15/U12	*	*	*	*	*	*	
		Not in conjunction with U29							
		Only in conjunction with P29+P31+[RRE/RRF/RVO/RVP/RVR]	*	*	*	*	*	*	
		Only in conjunction with P29+P31	*						
		Only in conjunction with U95		*	*		*		
		i.V.m. Code P31	○	○	○	○	○	○	0,00
776	Wider wheel arch for AMG wheels		○	○	○	○	○	S	0,00
		Not in conjunction with 11R/469/49R/83R/R70							
		Not in conjunction with 11R/49R/83R/R70	*	*	*	*	*	*	
79B	Preinstallation for digital radio		○	○	○	○	○	○	0,00
801	Technical modifications		○	○	○	○	○	○	0,00
817	Encapsulation for ATA alarm siren		○	○	○	○	○	○	0,00
820	Tourist vehicle		○	○	○	○	○	○	0,00
821	Country code Brazil		-	-	-	○	-	○	0,00
822	South Africa specification		○	○	○	○	○	○	0,00
823	Indicator plate fixing Switzerland		○	○	○	○	○	○	0,00
824	Additional parts for cold countries		○	○	○	○	○	○	0,00
829	Taiwan version		○	○	○	○	○	○	0,00

830	China specification		-	-	-	-	-	-	0,00
831	Indicator plate fixing Italia		○	○	○	○	○	○	0,00
834	New Zealand specification		○	-	-	○	○	○	0,00
835	South Korea specification		-	○	○	-	○	○	0,00
852	Sensor system for anti-theft alarm system		-	-	-	-	○	○	0,00
882	Interior monitoring system		○	○	○	○	○	○	0,00
885	Increased anti-theft protection		●	●	●	●	●	●	63,00
8R4	Complete winter (M+S) wheel-and-tyre assembly x 4		-	-	-	-	-	●	3.465,00
906	Armrest heating for driver and front passenger		○	○	○	○	○	○	0,00
	Available only as part of (P68)		*	*	*	*	*	*	
	Not in conjunction with 301A		*	*	*	*	*	*	
	Not in conjunction with 873		*	*	*	*	*	*	
	Only in conjunction with 275+P49+P68		*	*	*	*	*	*	
910	Alternator, with higher capacity		○	○	○	○	○	○	0,00
913	Air conditioning preinstallation for hot countries		○	○	○	○	○	○	0,00
919	Air Conditioning Enhancement package/improved cool		○	○	○	○	○	○	0,00
922	Reduced power version		-	-	-	-	-	-	0,00
926	Emission control system with EU4 technology		-	-	-	○	○	○	0,00
927	EU6 emissions standard		○	○	○	○	○	○	0,00
	Not in conjunction with U79			*					
	Only in conjunction with 6U7+972+U85			*					
	Only in conjunction with 971				*				
928	EU5 emission standard		-	-	-	-	-	-	0,00
943	Toll payment system		●	●	●	●	●	●	210,00
945	Emission control system China		-	-	-	-	-	-	0,00
961	Petrol particulate filter		-	-	-	○	○	○	0,00
	Only for left hand drive								
	Only for right hand drive					*			
966	COC document EU5 without registration certificate par		○	○	○	○	○	○	0,00
	Not in conjunction with 687/967		*	*	*	*	*	*	
967	COC document EU5 with registration certificate part II		○	○	○	○	○	○	0,00
	Not in conjunction with 687/966		*	*	*	*	*	*	
968	COC document EU6 without registration certificate par		○	○	○	○	○	○	0,00
969	COC document EU6 with registration certificate part II		○	○	○	○	○	○	0,00
971	Diesel particulate filter		○	-	○	-	-	-	0,00
972	Exhaust system with DPF Generation 2.0		○	○	-	-	-	-	0,00
973	Designation as owner-driver rental vehicle		○	-	○	○	○	○	0,00
981	Omission of vehicle registration document		○	○	○	○	○	○	0,00
986	Identification no. (US-VIN)		○	○	○	○	○	○	0,00
989	Identification label under windshield		○	○	○	○	○	○	0,00
997	Exhibition vehicle		○	○	○	○	○	○	0,00
999	Petrol particulate filter		-	-	-	○	-	-	0,00
			-	-	-	-	-	-	#VALUE!
	Only for left hand drive					*			
B01	EQ Boost starter-alternator		○	○	-	S	S	S	0,00
	invalid		*						
B08	Fanfares for Asia		○	○	○	○	○	○	0,00
B63	Sporty engine sound		-	-	S	S	S	-	0,00
E07	Location and tracking system		-	-	●	●	●	●	336,00
E08	Approval documentation for driving aids		●	●	●	●	●	●	115,50
	Only for left hand drive		*	*	*	*	*	*	
E09	Entrance guard		●	●	●	●	●	●	178,50
	Only for left hand drive		*	*	*	*	*	*	
E65	Steering wheel knob, left		●	●	●	●	●	●	420,00
	Only in conjunction with E08		*	*	*	*	*	*	
	Only for left hand drive		*	*	*	*	*	*	
E66	Steering wheel knob, right		●	●	●	●	●	●	420,00
	Only in conjunction with E08		*	*	*	*	*	*	
	Only for left hand drive		*	*	*	*	*	*	
E83	"Easy speed" leather-covered hand control unit		●	●	●	●	●	●	2.940,00
	Not in conjunction with E84/E92/E94		*	*	*	*	*	*	
	Only in conjunction with 275+E08+P49		*	*	*	*	*	*	
	Only for left hand drive		*	*	*	*	*	*	
E84	"Easy speed" hand control unit		●	●	●	●	●	●	2.310,00
	Not in conjunction with E83/E92/E94		*	*	*	*	*	*	

		Only in conjunction with 275+E08+P49	*	*	*	*	*	*	*	
		Only for left hand drive	*	*	*	*	*	*	*	
E85	Belt buckle opener		●	●	●	●	●	●	●	183,75
		Only for left hand drive	*	*	*	*	*	*	*	
E87	Pedal cover		●	●	●	●	●	●	●	525,00
		Only in conjunction with E08	*	*	*	*	*	*	*	
		Only for left hand drive	*	*	*	*	*	*	*	
E88	Combination switch moved to the right		●	●	●	●	●	●	●	241,50
		Only in conjunction with E08	*	*	*	*	*	*	*	
		Only for left hand drive	*	*	*	*	*	*	*	
E89	Accelerator pedal moved to the left (electronic)		●	●	●	●	●	●	●	1.680,00
		Only in conjunction with E08	*	*	*	*	*	*	*	
		Only for left hand drive	*	*	*	*	*	*	*	
E92	Pedal extenders (2)		●	●	●	●	●	●	●	630,00
		Not in conjunction with E83/E84	*	*	*	*	*	*	*	
		Only in conjunction with E08	*	*	*	*	*	*	*	
		Only for left hand drive	*	*	*	*	*	*	*	
E94	Left seat repositioning to the rear		●	●	●	●	●	●	●	651,00
		Not in conjunction with E83/E84	*	*	*	*	*	*	*	
		Only in conjunction with E08	*	*	*	*	*	*	*	
		Only for left hand drive	*	*	*	*	*	*	*	
E95	Right seat repositioning to the rear		●	●	●	●	●	●	●	651,00
		Only in conjunction with E08	*	*	*	*	*	*	*	
		Only for left hand drive	*	*	*	*	*	*	*	
K32	Active Lane Change Assist		○	○	○	○	○	○	○	0,00
K33	Extended automatic Re-start in traffic jams		○	○	○	○	○	○	○	0,00
		Not in conjunction with 234/239/243/258/355/504/868/PBF								
		Not in conjunction with 234/243/258/504	*	*	*	*	*	*	*	
		Not in conjunction with 239	*	*	*	*	*	*	*	
		Only in conjunction with 01U+14U+16U+17U+233+235+274+367+448+513+546+876+891+K34+P49								
		Only in conjunction with 233+235+365+513+546+K34+P49	*	*	*	*	*	*	*	
K34	Route-based speed adaptation		○	○	○	○	○	○	○	0,00
		Not in conjunction with 234/239/243/258/355/504/868/PBF								
		Not in conjunction with 234/243/504	*	*	*	*	*	*	*	
		Not in conjunction with 239					*			
		Not in conjunction with 258					*	*		
		Only in conjunction with 01U+14U+16U+17U+233+274+367+448+513+546+876+891+P49								
		Only in conjunction with 233+365+513+546+P49	*	*	*	*	*	*	*	
L	Left-hand drive		○	○	○	○	○	○	○	0,00
P53	Fine particle sensor		-	○	-	-	○	○		0,00
PYB	SE Package		-	-	-	-	●	-		0,00
PYB	SE Package		●	●	●	-	-	-		0,00
PYB	SE Package		-	-	-	-	-	●		0,00
PYB	SE Package		-	-	-	●	-	-		0,00
PYC	SE Plus Package		-	-	-	-	-	●		0,00
PYH	AMG Line		●	●	-	●	-	-		3.180,00
			-	-	●	-	●	-		2.930,00
PYH	AMG Line		-	-	-	-	-	●		0,00
PYM	Advantage Package		-	-	-	-	-	●		3.906,00
			●	●	●	●	●	-		3.812,00
		i.V.m. Code PYH	●	●	●	●	●	-		3.600,00
PYN	Premium Package		-	-	-	-	-	●		6.484,00
			●	●	●	●	●	-		6.396,00
		i.V.m. Code PYH	●	●	●	●	●	-		6.196,00
PYO	Premium Plus package		-	-	-	-	-	●		8.726,00
			●	●	●	●	●	-		8.644,00
		i.V.m. Code PYH	●	●	●	●	●	-		8.456,00
R	Right-hand drive		●	●	●	●	●	●		1.905,75
R02	All-season tyres		-	-	-	-	○	○		0,00
R05	Summer tyres		-	-	-	-	-	○		0,00
		Not in conjunction with Z50/R01						*		
		Only in conjunction with [RRE/RRF]						*		
U01	Status display for rear seat belts in instrument cluster		○	○	○	○	○	○		0,00
U10	Automatic front passenger airbag deactivation		○	○	○	○	○	○		0,00
U16	Sports exhaust system		-	-	-	○	○	-		0,00

U46	Omission fixed rear wing		○	–	–	○	–	–	0,00
		Not in conjunction with 301A/818A/U12	*			*			
		Only in conjunction with [RRE/RRF/RVO/RVP/RVR]	*			*			
U60	Pedestrian protection		○	○	○	○	○	○	0,00
U79	BlueTEC diesel emission control system including AdBl		S	●	S	–	–	–	0,00
U79		Not in conjunction with 6U7/927		*					
U79		Only in conjunction with U85		*					
U80	115 V socket		–	–	–	–	●	●	126,00
U90	Low-Line package China		–	–	–	–	–	–	0,00
U92	High-Line-package China		–	–	–	–	–	–	0,00
Z01	Paint not feat.on standard sample card		○	○	○	○	○	○	0,00
		Not in conjunction with Z02/Z98	*	*	*	*	*	*	
		Only in conjunction with 000U+524	*	*	*	*	*	*	
Z02	Paint not feat.on standard sample card		○	○	○	○	○	○	0,00
		Not in conjunction with Z01/Z98	*	*	*	*	*	*	
		Only in conjunction with 000U+524	*	*	*	*	*	*	
Z98	Paint not feat.on standard sample card		○	○	○	○	○	○	0,00
		Not in conjunction with Z01/Z02	*	*	*	*	*	*	
		Only in conjunction with 000U+524	*	*	*	*	*	*	
B12	Tyre-change toolkit		○	○	○	○	○	○	0,00
482	Fire extinguisher		●	●	●	●	●	●	0,00
70B	Fluorescent jacket for driver		●	●	●	●	●	●	5,25
		Not in conjunction with 71B	*	*	*	*	*	*	
71B	Safety vests for driver and passengers		●	●	●	●	●	●	26,25
		Not in conjunction with 70B	*	*	*	*	*	*	
293	Sidebags in rear		●	●	●	●	●	●	399,00
294	Kneebag		S	S	S	S	S	S	0,00
258	Active Brake Assist		●	●	●	●	●	●	0,00
258		Not in conjunction with 233/239/23P/266/292/546/K32/K33/K34/P20	*						
258		Not in conjunction with 233/239/23P/266/546/K32/K33/K34/P20							
258		Not in conjunction with 233/546/K34					*	*	
258		Not in conjunction with 23U/K33	*	*	*	*	*	*	
258		Not in conjunction with 266						*	
258		Only in conjunction with 243	*	*	*	*	*	*	
292	PRE-SAFE® impulse side		○	○	○	○	○	○	0,00
		Available only as part of (P20)	*	*	*	*	*	*	
		Not in conjunction with 234/239/23P/243/258	*						
		Not in conjunction with 234/504	*	*	*	*	*	*	
		Only in conjunction with 274+P20+P49	*						
		Only in conjunction with 365+513+546+K34+P20+P49	*	*	*	*	*	*	
22P	Lane Tracking package		●	●	●	●	●	●	819,00
234	Blind Spot Assist		●	●	●	●	●	●	472,50
		Not in conjunction with 233/23P/266/292/546/K32/K33/K34/P20	*						
		Not in conjunction with 233/23P/266/546/K32/K33/K34/P20							
		Not in conjunction with 233/23U/266/546/K33/K34	*	*	*	*	*	*	
		Not in conjunction with 23P/292/P20	*	*	*	*	*	*	
		Only in conjunction with 243+274+P49	*						
		Only in conjunction with 243+P49	*	*	*	*	*	*	
		Only in conjunction with 258						*	
		i.V.m. Code 22P	○	○	○	○	○	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	0,00
23P	Driving Assistance package		●	●	●	●	●	●	2.026,50
		Includes codes 233+266	*	*	*	*	*	*	
		Not in conjunction with 234/239/243/258/292/P20	*						
		Not in conjunction with 234/239/243/258/P20							
		Not in conjunction with 234/23U/504	*	*	*	*	*	*	
		Only in conjunction with 274+P49	*						
		Only in conjunction with 365+513+546+K34+P49	*	*	*	*	*	*	
		i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	1.554,00
243	Active Lane Keeping Assist		○	○	○	○	○	○	0,00
		Not in conjunction with 233/23P/266/292/546/K32/K33/K34/P20	*						
		Not in conjunction with 233/23P/266/546/K32/K33/K34/P20							
		Not in conjunction with 233/23U/266/546/K33/K34	*	*	*	*	*	*	
		Only in conjunction with 258						*	
266	Active Steering Assist		○	○	○	○	○	○	0,00

		Not in conjunction with 234/239/243/258	*								
		Not in conjunction with 234/243	*	*	*	*	*	*			
		Not in conjunction with 258							*		
475	Tyre pressure monitoring system		●	●	●	●	●	—			320,25
			—	—	—	—	—	○			0,00
		i.V.m. S-Code 6P5	○	○	○	○	○	—			0,00
504	Speed Limit Assist		○	○	○	○	○	○			0,00
		Not in conjunction with 233/23U/513/546/K33/K34	*	*	*	*	*	*			
		Not in conjunction with 23P/292/P20	*	*	*	*	*	*			
		Not in conjunction with 513/546/811/865/K32/K33/K34	*								
		Only in conjunction with 243	*	*	*	*	*	*	*		
		Only in conjunction with 868+876+891+B18	*								
		Only in conjunction with [258]							*		
513	Traffic Sign Assist		●	●	●	●	●	●			309,75
		Not in conjunction with 355/504/868/PBF	*								
		Not in conjunction with 504	*	*	*	*	*	*	*		
		Only in conjunction with 01U+12U+14U+16U+17U+367+448+876+891	*								
		Only in conjunction with 01U+14U+16U+17U+367+448+876+891									
		Only in conjunction with 365	*	*	*	*	*	*	*		
		i.V.m. Code PYB	○	○	○	○	○	○			0,00
546	Active Speed Limit Assist		○	○	○	○	○	○			0,00
		Not in conjunction with 234/239/243/258/355/504/868/PBF	*								
		Not in conjunction with 234/243/504	*	*	*	*	*	*	*		
		Not in conjunction with 239						*			
		Not in conjunction with 258						*	*		
		Only in conjunction with 01U+12U+14U+16U+17U+233+274+367+448+513+876+891+K34+P49	*								
		Only in conjunction with 01U+14U+16U+17U+233+274+367+448+513+876+891+K34+P49									
		Only in conjunction with 233+365+513+K34+P49	*	*	*	*	*	*	*		
P20	Driving Assistance package Plus		●	—	●	—	●	●			2.551,50
			—	●	—	●	—	—			2.520,00
		Includes codes 233+266+292	*	*	*	*	*	*	*		
		Not in conjunction with 234/239/23P/243/258	*								
		Not in conjunction with 234/504	*	*	*	*	*	*	*		
		Only in conjunction with 274+P49	*								
		Only in conjunction with 365+513+546+K34+P49	*	*	*	*	*	*	*		
		i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●			2.079,00
218	Reversing camera		●	●	●	●	●	●			420,00
		Not in conjunction with 501/P47	*								
		Not in conjunction with P47	*	*	*	*	*	*	*		
		i.V.m. Code PYB/P44	○	○	○	○	○	○			0,00
235	Active Parking Assist with PARKTRONIC		●	●	●	●	●	●			782,25
		i.V.m. Code P44/P47	○	○	○	○	○	○			0,00
P44	Parking package with reversing camera		●	●	●	●	●	●			1.097,25
		Includes codes 218+235	*	*	*	*	*	*	*		
		Includes codes 235+218	*								
		Not in conjunction with 501/P47	*								
		Not in conjunction with P47	*	*	*	*	*	*	*		
		i.V.m. Code PYM	○	○	○	○	○	○			0,00
P47	Parking Package with 360-degree camera		●	●	●	●	●	●			1.580,25
		Includes codes 235+501	*	*	*	*	*	*	*		
		Not in conjunction with 218/P44	*	*	*	*	*	*	*		
		Only in conjunction with 274+P49	*								
		Only in conjunction with P49	*	*	*	*	*	*	*		
		i.V.m. Code PYN	○	○	○	○	○	○			0,00
		i.V.m. Code PYO	○	○	○	○	○	○			0,00
915	Fuel tank with a capacity of 80 litres		—	—	—	—	●	●			105,00
		Not in conjunction with 916					*	*			
		i.V.m. Code PYB	—	—	—	—	○	○			0,00
916	Fuel tank with a capacity of 66 litres		●	●	●	—	—	—			52,50
			—	—	—	○	S	S			0,00
		Not in conjunction with 915					*	*			
		i.V.m. Code PYB	○	○	○	—	—	—			0,00
B59	DYNAMIC SELECT		S	S	S	S	S	—			0,00
U29	Braking system with larger brake discs on the front ax		●	●	—	●	—	—			262,50
			—	—	○	—	○	—			0,00

		Not in conjunction with 301A/818A/P14/P15/U12			*		*		
		Only in conjunction with [RRE/RRF/RVO/RVP/RVR]			*		*		
		i.V.m. Code PYH	○	○	-	○	-	-	0,00
U85	AdBlue® tank with 23.5-litre capacity		S	○	S	-	-	-	0,00
459	DYNAMIC BODY CONTROL suspension with adjustable		●	●	●	●	●	-	1.039,50
		Not in conjunction with 489/677	*						
		Only for left hand drive			*		*		
489	AIR BODY CONTROL		●	●	●	●	●	-	1.995,00
		Not in conjunction with 459/677	*						
		Not in conjunction with 677			*		*		
489	AMG RIDE CONTROL+		-	-	-	-	-	S	0,00
677	Lowered comfort suspension		S	S	S	S	S	-	0,00
		Not in conjunction with 459/489	*						
		Not in conjunction with 489			*		*		
481	Underguard		●	●	●	●	●	-	115,50
421	9G-TRONIC		S	S	S	S	S	-	0,00