

From	<b>Price list B-Class</b>
17-Okt-17	<b>CY 17/2, MY 808+058, SR 23. October 2017</b>
	<div> <div>National Standard</div> <div>Delta to NST</div> </div> <div> <div>National Package</div> <div>Not for Greece</div> </div>
	● available at extra charge    ○ available at no extra charge    ⓘ annotations existing S standard equipment    - not available

## National Package

## Not for Greece

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

B Sportstourer	
246.211	B 160 d
246.212	B 180 d
246.208	B 200 d
246.202	B 200 d 4MATIC
246.203	B 220 d
246.205	B 220 d 4MATIC
246.241	B 160
246.242	B 180
246.243	B 200
246.245	B 220
246.247	B 220 4MATIC
246.244	B 250
246.246	B 250 4MATIC

[illegible]

From	<b>Price list B-Class</b>
17-OKT-17	<b>CY 17/2, MY 808+058, SR 23. October 2017</b>
	<div> <div>National Standard</div> <div>Delta to NST</div> </div> <div> <div>National Package</div> <div>Not for Greece</div> </div>
	● available at extra charge    ○ available at no extra charge    U annotations existing S standard equipment    - not available

## National Package

## Not for Greece

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]



From	<b>Price list B-Class</b>
17-OKT-17	<b>CY 17/2, MY 808+058, SR 23. October 2017</b>
	<div> <div>National Standard</div> <div>Delta to NST</div> </div> <div> <div>National Package</div> <div>Not for Greece</div> </div>
	● available at extra charge    ○ available at no extra charge    U annotations existing S standard equipment    - not available

		B Sportstourer												LLP	
Code	Designation	246.211	246.212	246.208	246.202	246.203	246.205	246.241	246.242	246.243	246.245	246.247	246.244	246.246	
	*BM 246.245 only for South-Korea														
	<b>Designation</b>														
	1_consisting of Code 840 (certain countries only), 01R	●	●	●	●	●	●	●	●	●	●	●	●	●	409,50
	2_only in conjunction with Code P27, P59 or 950. Code 631 or 632. Code 01R or 646. Code 612 only in conjunction with with Code 950	●	●	●	●	●	●	●	●	●	●	●	●	●	787,50
	3_not in conjunction with Code 965, U63, 4U3	●	●	●	●	●	●	●	●	●	●	●	●	●	
	<b>i.V.m. Code 950</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	
	<b>i.V.m. Code P59</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	
<b>P59</b>	<b>Urban</b>	-	-	-	U	-	U	-	-	-	●	-	U	●	829,50
	Delta to NST code 55R (710 EUR)	U	U	-	-	-	●	●	●	●	-	-	-	-	850,50
	Delta to NST code 55R (460 EUR)	-	-	U	-	U	-	-	-	●	-	●	-	-	929,25
	Delta to NST code R27 (250 eur)	-	-	-	-	-	-	-	-	●	-	-	-	-	1149,75
															1596,00
	1_only in conjunction with Code 105A, 111A, 118A, 201A, 204A, 207A, 611A or 618A), 280, (310/938 or U63), 543, (H81/734 or 736) Code 485 or 677 or 482														
	2_Code R04 or R43, 01R, 25R, 44R, 646, 612 or 791. Not in conjunction with Code 498, 950, P27, P39												★		
	3_Code R04 or R43, 01R, R15, 25R or 44R . In case of Code 643 R78 or 55R is Code 645 possible with mentioned tires	★	★	★	★	★	★								
	4_not in conjunction with Code 950, P27, P39, P51 or 4U3														
<b>PEK</b>	<b>WhiteArt Edition</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	945,00
	1_consisting of Upholstery 671A, Paint 650U, 191U, 696U, 761U, 787U. H74 or H81. U66 or U26. U13 or 261. 280 or 277. U15 or U03. Code RUT, RUU, 678. In conjunction with Code P55 Code 612, RUT or RUU.														
	2_only in conjunction with Code 950														
	3_not in conjunction with Code 58U, P34, P39, P59, 450, 965, 970, 974, 975, U63														
	4_for certain countries only														
	<b>i.V.m. Rechtslenker</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	777,00
<b>U59</b>	<b>Seat comfort package</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	246,75
	1_not in conjunction with upholstery 001A														
	2_in conjunction with Code 111A, 115A, 118A, 121A, 201A, 204A, 207A, 611A, 618A, 671A or P27 in scope of delivery														
	<b>i.V.m. Code 950,P27,P34,P39,P59,U63</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
<b>U62</b>	<b>Light and sight package</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	341,25
	1_consisting of Code 345, 543	-	-	○	○	○	○	○	○	○	○	○	○	○	0,00
	<b>i.V.m. Code U63</b>	-	-	○	○	○	○	○	○	○	○	○	○	○	0,00
<b>U63</b>	<b>Basic driving school package</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	519,75
	1_including Code U59, U62, 931														
	2_not in conjunction with Code 310, 840, P55, 965, 970, 974, 975														
	3_for certain countries only														
<b>U90</b>	<b>Low-Line package China</b>	-	-	-	-	-	-	-	-	○	-	-	-	-	0,00
	1_only for China														
<b>U91</b>	<b>Mid-Line-package China</b>	-	-	-	-	-	-	-	-	○	-	-	-	-	0,00
	1_only for China														
<b>U92</b>	<b>High-Line-package China</b>	-	-	-	-	-	-	-	-	○	-	-	-	-	0,00
	1_only for China														
<b>498</b>	<b>Japan specification</b>	-	-	-	-	-	-	-	○	-	-	○	-	U	0,00
	1_not valid													★	
<b>00B</b>	<b>Owner's Manual and Service Booklet - Danish</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
<b>01B</b>	<b>Owner's Manual and Service Booklet - Dutch</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
<b>01R</b>	<b>45.7 cm (18-inch) 5-twin-spoke light-alloy wheels</b>	-	-	●	-	●	-	-	-	●	●	●	-	-	766,50
	Delta to NST code 55R (460 EUR)	●	●	-	-	-	-	●	●	-	-	-	-	-	766,50
	Delta to NST code 55R (710 EUR)	-	-	-	●	-	●	-	-	-	-	-	●	●	525,00
	1_in conjunction with Code R01 is Code R66 possible														
	2_not in conjunction with Code 645 is Code R66 not possible														
	3_not in conjunction with Code 950, 965														
	4_for certain countries only														
	<b>i.V.m. Code P27</b>	-	-	-	●	-	●	-	-	-	-	-	●	●	525,00
		●	●	●	-	●	-	●	●	●	●	●	-	-	892,50

From	<b>Price list B-Class</b>
17-OKT-17	<b>CY 17/2, MY 808+058, SR 23. October 2017</b>
	<div> <div>National Standard</div> <div>Delta to NST</div> </div> <div> <div>National Package</div> <div>Not for Greece</div> </div>
	● available at extra charge    ○ available at no extra charge    ○ annotations existing S standard equipment    - not available

## National Package

## Not for Greece

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]

0,00  
525.00

*BM 246.245 only for South-Korea		24E	24E	24E	24E	24E	24E	24E	24E	24E	24E	24E	24E	24E	24E	24E	LLP
Code	Designation	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	i.V.m. Code P55	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	525,00
02B	Owner's Manual and Service Booklet - German	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
03B	Owner's Manual and Service Booklet - Russian	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
04B	Owner's Manual and Service Booklet - Finnish	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
05B	Owner's Manual and Service Booklet - English	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
06B	Owner's Manual and Service Booklet - Italian	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
07B	Owner's Manual and Service Booklet - French	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
07U	MB apps for Audio 20 without MBCONNECT	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	52,50
	1_only in conjunction with Code 505, 520 or 522																
	2_not in conjunction with Code 11U																
	3_not in conjunction with Code 360 or 362 (for certain countries only)																
08B	Owner's Manual and Service Booklet - Spanish	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
09B	Owner's Manual and Service Booklet - Portuguese	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
10B	Owner's Manual and Service Booklet - Swedish	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
11B	Owner's Manual and Service Booklet - Arabic	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
11U	Remote Online	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	157,50
	1_only in conjunction with Code 360, 362																
	2_in scope of delivery from Code 531																
	3_not in conjunction with Code 07U																
	i.V.m. Code 531	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
12B	Owner's Manual and Service Booklet - Engl. USA/CAN	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
12U	Concierge Service	-	-	-	-	-	-	-	-	○	○	-	-	○	-	-	0,00
	1_only in conjunction with Code 830, 362. Not in conjunction with Code U90																
13B	Owner's Manual and Service Booklet - Norwegian	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
14B	Owner's Manual and Service Booklet - Greek	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
14U	Smartphone integration package	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	315,00
	1_only in conjunction with Code 16U, 17U																
	2_for certain countries standard with Code 531, 532																
	3_in conjunction with Code 531: Smartphone integration																
	4_for certain countries only																
	i.V.m. Code 531/532	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
15B	Owner's Manual and Service Booklet - Turkish	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
15U	Pre-installation for Mercedes-Benz Link	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	1_only in conjunction with Code 505, 520, 522 or 49U																
	2_in conjunction with 19U and 965 Code 531 is possible																
16B	Owner's Manual and Service Booklet - Polish	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
16U	Apple CarPlay	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
17B	Owner's Manual and Service Booklet - Czech	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
17U	Android Auto	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	1_only in conjunction with Code 14U, 505, 520, 522, 531, 532																
18B	Owner's Manual and Service Booklet - Engl. S. Am.	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
18U	Baidu Carlife	-	-	-	-	-	-	-	-	○	○	-	-	○	-	-	0,00
	1_only in conjunction with Code 830, 14U, 520 or 522																
19B	Owner's Manual and Service Booklet - French S. Am.	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
19U	Mercedes-Benz Link Taxi	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	157,50
	1_only in conjunction with Code 965 and 15U																
1R1	winter (M+S) wheel and tyre assembly x 4	●	●	-	-	-	-	●	●	-	-	-	-	-	-	-	577,50
	1_for certain countries only																
	2_only in conjunction with Code R00. Code 651 or 652																
	3_not in conjunction with Code 965, 970, 974, 975, P55, P59, 950 or R66																
1R2	winter (M+S) wheel and tyre assembly x 4	●	●	●	-	⓪	-	●	●	●	-	⓪	-	-	-	-	840,00
	1_for certain countries only																
	2_only in conjunction with Code 651 or 652.																
	3_not in conjunction with Code 950																
20B	Owner's Manual and Service Booklet - Spanish S. Am.	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00

From  
17-ОКТ-17

## Price list B-Class

CY 17/2, MY 808+058, SR 23. October 2017

National Standard

National Package

Delta to NST

Not for Greece

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

B Sportstourer

246.211	B 160 d	246.212	B 180 d	246.208	B 200 d	246.202	B 200 d 4MATIC	246.203	B 220 d	246.205	B 220 d 4MATIC	246.241	B 160	246.242	B 180	246.243	B 200	246.245	B 220	246.247	B 220 4MATIC	246.244	B 250	246.246	B 250 4MATIC
---------	---------	---------	---------	---------	---------	---------	----------------	---------	---------	---------	----------------	---------	-------	---------	-------	---------	-------	---------	-------	---------	--------------	---------	-------	---------	--------------

LLP

Code	*BM 246.245 only for South-Korea Designation	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	246	LLP
213	<b>Sports Direct-Steer system</b> 1_only in conjunction with Code 677 or 459 2_only for certain countries 3_not in conjunction with Code 4U3	○	U	○	○	○	○	○	○	U	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
218	<b>Reversing camera</b> 2_only for certain countries	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	351,75
21B	<b>Owner's Manual and Service Booklet - Portug. S. Am.</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
228	<b>Auxiliary heater</b>  1_for certain countries only in conjunction with Code B24 2_for certain countries only i.V.m. Code 360/362	-	-	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1312,50
22B	<b>Owner's Manual and Service Booklet - Japanese</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
232	<b>Garage door opener (frequency range 284-390 MHz)</b>  1_only in conjunction with Code P49, U62 2_for certain countries only	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●	●	●	●	236,25	
234	<b>Blind Spot Assist</b>  1_for certain countries only i.V.m. Code 22P	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	472,50
		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
235	<b>Parking Pilot</b> 1_only for certain countries	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	708,75
239	<b>Distance Pilot DISTRONIC</b> 1_only in conjunction with Code 429 2_not in conjunction with Code 258 or 440 3_Certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	903,00
23B	<b>Owner's Manual and Service Booklet - simpl. Chinese</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
23Z	<b>Pre-installation for TETRA mobile radio, Motorola</b> 1_only in conjunction with Code 970, 974 or 975	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	147,00
241	<b>Front seat left, electrically adjustable memory switch</b> 1_only in conjunction with Code 275 2_Right-hand-drive vehicles only 3_Not in conjunction with Code 001A	●	●	●	-	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	299,25
242	<b>Front passenger seat, electrically adjustable with memory function</b> 1_only in conjunction with Code 275 2_only for Left Hand Drive 3_not in conjunction with Code U57, 842 or 001A	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	299,25
245	<b>Compass</b> 1_only in conjunction with Code P49, U62, 460 or 494 3_not in conjunction with Code 531	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●	●	●	●	110,25	
248	<b>Rear seats with integrated child seats</b> 1_only in conjunction with Code 105A, 111A or 118A 2_not in conjunction with Code U57, P34, P39 or 950 3_not in conjunction with Code 4U3 4_for certain countries only i.V.m. Code 965	●	U	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	357,00
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	115,50
249	<b>Interior mirror and driver's exterior mirror automatically dimming</b> 1_only in conjunction with Code P49	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
24B	<b>Owner's Manual and Service Booklet - trad. Chinese</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
24Z	<b>Pre-installation for TETRA mobile radio, Sepura</b> 1_only in conjunction with Code 970, 974 or 975	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	147,00
258	<b>Active Brake Assist</b> 2_only for certain countries; Serie in bestimmten Ländern	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0,00
25B	<b>Owner's Manual and Service Booklet - Korean</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
25R	<b>43.2 cm (17-inch) 10-spoke light-alloy wheels</b>  2_not in conjunction with Code 950, P51, P55 or 4U3 i.V.m. Code P27	-	-	-	○	-	○	-	-	-	-	-	-	-	-	-	-	-	-	-	-	○	○	○	○	0,00	
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	693,00
		●	●	-	-	-	-	●	●	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	955,50
		-	-	-	○	-	○	-	-	-	-	-	-	-	-	-	-	-	-	-	-	○	○	○	○	○	0,00

From  
17-OKT-17

## Price list B-Class

CY 17/2, MY 808+058, SR 23. October 2017

National Standard

National Package

Delta to NST

Not for Greece

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

B Sportstourer

	246.211	246.212	246.208	246.202	246.203	246.205	246.241	246.242	246.243	246.245	246.247	246.244	246.246	
	B 160 d	B 180 d	B 200 d	B 200 d 4MATIC	B 220 d	B 220 d 4MATIC	B 160	B 180	B 200	B 220	B 220 4MATIC	B 250	B 250 4MATIC	
	●	●	●	●	●	●	●	●	●	●	●	●	●	LLP

LLP

535,50

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00

0,00



From	<b>Price list B-Class</b>
17-Окт-17	<b>CY 17/2, MY 808+058, SR 23. October 2017</b>
	<div> <div>National Standard</div> <div>Delta to NST</div> </div> <div> <div>National Package</div> <div>Not for Greece</div> </div>
	● available at extra charge    ○ available at no extra charge    U annotations existing S standard equipment    - not available

[illegible]



From	<b>Price list B-Class</b>
17-Окт-17	<b>CY 17/2, MY 808+058, SR 23. October 2017</b>
	<div> <div>National Standard</div> <div>Delta to NST</div> </div> <div> <div>National Package</div> <div>Not for Greece</div> </div>
	● available at extra charge    ○ available at no extra charge    U annotations existing S standard equipment    - not available

## National Package

## Not for Greece

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]

LLP	
	0,00
	0,00
	1323,00
	173,25
	0,00
	0,00
	1202,25
	0,00
	0,00
	0,00
	945,00
	1092,00
	787,50
	0,00
	0,00
	0,00
	0,00
	320,25
	0,00
	472,50
	0,00
	0,00
	105,00
	0,00
	0,00

\*BM 246.245 only for South-Korea  
Designation

1\_only in conjunction with Code 505, 520, 522 or 531  
2\_not in conjunction with Code 379, 536, 537, 862 or 865  
3 for certain countries only

Owner's Manual and Service Booklet - Estonian

Owners manual and service record - Serbian	
--	--

winter (M+S) wheel and tyre assembly x 4	
--	--

1\_for certain countries only  
2\_only in conjunction with Code 651 or 652  
3\_not in conjunction with Code 950

Rear armrest

**1\_not in conjunction with Code 001A  
in conjunction with Code U57**

Owners manual and servive record - ukrainian

**Panoramic sliding sunroof**  
 1\_only in conjunction with Code 543, 51U  
 2\_not in conjunction with Code 342, 970, 974, 975  
 3\_not in conjunction with Code 4U3

### Steering wheel shift paddles

1 only in conjunction with Code 429

Cruise control

1 not in conjunction with Code 239

Multifunction steering wheel

Taxi version international

1\_only in conjunction with Code 105A, 111A, 118A, 121A, 201A, 204A, 207A, 965, 334 or 335. 837

<b>Suspension with Adaptive Damping system</b> 1_only in conjunction with Code 213, B59 2_not in conjunction with Code 482, 483, 485, 486, 550, 677, 4U3 <b>i.V.m. Code 950</b>
--

	Canada specification
Number of observations	60
Number of countries	10
Time period	1987-1996
Dependent variable	Change in the share of total population aged 65 years and over
Control variables	Country fixed effects, year fixed effects, GDP per capita, life expectancy at birth, average number of children per woman, average number of years of schooling, average number of years of experience, average number of years of migration, average number of years of residence in Canada, average number of years of residence in the United States, average number of years of residence in other countries
Model	Panel regression model with country fixed effects and year fixed effects
Results	The results show that the share of the total population aged 65 years and over has increased significantly in all ten countries from 1987 to 1996. The increase was largest in Japan (from 14.5% to 18.5%) and Germany (from 14.5% to 17.5%). The increase was smallest in Australia (from 14.5% to 15.5%).

Instrument cluster with display in miles and English lettering
1 for certain countries only

Instrument cluster with Asian characters

1 for certain countries only

Diesel particulate filter

1\_not in conjunction with Code 926  
2 Standard in certain countries

## Tyre pressure monitoring system

1 Standard in certain countries

für bestimmte Länder Serie

**Event Keeping Assist**

1 only in conjunction with Code 280

2 not in conjunction with Code 234

i V m Code 22P

Tyre pressure loss warning system

1 for certain countries only

	Suspension with higher ground clearance
--	---

1 not in conjunction with Code 4113

**Comfort suspension**

1\_not in conjunction with Code 4U3

2\_in conjunction with Code 950 possible then omission 213

Electrically folding exterior mirrors

**From Price list B-Class**
**17-OKT-17 CY 17/2, MY 808+058, SR 23. October 2017**
**National Standard**
**National Package**
**Delta to NST**
**Not for Greece**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

**B Sportstourer**

	246.211	246.212	246.208	246.202	246.203	246.205	246.241	246.242	246.243	246.245	246.247	246.244	246.246	
	B 160 d	B 180 d	B 200 d	B 200 d 4MATIC	B 220 d	B 220 d 4MATIC	B 160	B 180	B 200	B 220	B 220 4MATIC	B 250	B 250 4MATIC	
	●	●	●	●	●	●	●	●	●	●	●	●	●	LLP
<b>505</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	<b>52,50</b>
<b>513</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	<b>0,00</b>
<b>518</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	<b>52,50</b>
<b>51U</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	<b>0,00</b>
<b>520</b>	S	S	S	S	S	S	S	S	S	S	S	S	S	<b>0,00</b>
<b>522</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	<b>315,00</b>
<b>524</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	<b>420,00</b>
<b>531</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	<b>168,00</b>
<b>532</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	<b>2845,50</b>
<b>536</b>	-	-	-	-	-	-	-	-	-	-	-	●	●	<b>3108,00</b>
<b>537</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	<b>1365,00</b>
<b>538</b>	S	S	S	S	S	S	S	S	S	S	S	S	S	<b>367,50</b>
<b>543</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	<b>446,25</b>
<b>550</b>	●	U	●	●	●	●	●	●	●	●	●	●	●	<b>0,00</b>
<b>551</b>	●	●	●	●	●	●	●	●	●	●	●	●	●	<b>0,00</b>
<b>55R</b>	-	-	●	-	●	-	-	-	●	●	-	-	-	<b>829,50</b>
<b>567</b>	○	○	○	○	○	○	○	○	○	○	○	○	○	<b>262,50</b>
<b>580</b>	S	S	S	S	S	S	S	S	S	S	S	S	S	<b>0,00</b>

\*BM 246.245 only for South-Korea

**Designation**

1\_only in conjunction with Code P49  
2\_only for certain countries

**Audio 20 CD**

1\_only in conjunction with Code 818 and Code 351 and 360 (for certain countries only)

**Traffic Sign Assist**

1\_only in conjunction with Code 531  
2\_for certain countries only

**Media Interface cable kit**

1\_not in conjunction with Code 14U with Code 505, 520, 522  
2\_for certain countries only

**Roof liner in black fabric**

1\_only in conjunction with Code 413, 950, P27, P34, P39, P51, P59. Or Code 105A or 111A in conjunction with Code 965

**Audio 20 USB**

1\_only in conjunction with Code 15U, 351 and 360 (for certain countries only)

**Audio 20 CD including preinstallation for Garmin® MAP PILOT**

1\_only in conjunction with Code 818, 15U

**i.V.m. Code 367**
**Transport protection**

1\_for certain countries only, not in conjunction with Code 820

**COMAND Online**

1\_consisting of Code 814 or 815. Code 351, 360, 367, 502, 513, 11U (for certain countries only)

**i.V.m. Code 367**
**COMAND Japan**

1\_only in conjunction with Code 815, 14U  
2\_for certain countries only

**Sirius satellite radio**

1\_for certain countries only

2\_not in conjunction with Code 386

**Digital radio**

1\_only in conjunction with Code 505, 522 or 531  
2\_not in conjunction with Code 386, 597, P58, Z97  
3\_for certain countries only

**ATTENTION ASSIST**
**Sun visor with illuminated vanity mirror**

1\_only in conjunction with Code 413, 950, P27, P51, P59 or U62

**Trailer coupling with ESP® trailer stabilisation**

1\_not in conjunction with Code 4U3 for the B 180 d (246.212) For the B 180 (246.242) Code 4U3 is Code 550 possible  
2\_for certain countries only

**Anti-theft alarm system**

1\_scope of delivery of Code P54 in certain countries  
2\_for certain countries only

**in Verbindung mit P54**

For certain count. scope of delivery of Code P54

**40.6 cm (16-inch) 10-spoke light-alloy wheels**
**NATIONAL STANDARD**

1\_not in conjunction with Code 950, P55 or P59  
2\_in conjunction with Code R02 Code R66 not possible  
i.V.m. Code P27

**Rear seat fore/aft adjustment**

1\_only in conjunction with Code U57

**Air conditioning system**



From	Price list B-Class
17-Okt-17	CY 17/2, MY 808+058, SR 23. October 2017
	<div> <div>National Standard</div> <div>Delta to NST</div> </div> <div> <div>National Package</div> <div>Not for Greece</div> </div>
	● available at extra charge    ○ available at no extra charge    ○ annotations existing S standard equipment    - not available

## National Package

## Not for Greece

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]

From	Price list B-Class				
17-OKT-17	CY 17/2, MY 808+058, SR 23. October 2017				
	<table> <tr> <td>National Standard</td><td>National Package</td></tr> <tr> <td>Delta to NST</td><td>Not for Greece</td></tr> </table>	National Standard	National Package	Delta to NST	Not for Greece
National Standard	National Package				
Delta to NST	Not for Greece				
	<p>● available at extra charge    ○ available at no extra charge    ○ annotations existing</p> <p>S standard equipment    - not available</p>				

[illegible]



From	Price list B-Class				
17-OKT-17	CY 17/2, MY 808+058, SR 23. October 2017				
	<table> <tr> <td>National Standard</td><td>National Package</td></tr> <tr> <td>Delta to NST</td><td>Not for Greece</td></tr> </table>	National Standard	National Package	Delta to NST	Not for Greece
National Standard	National Package				
Delta to NST	Not for Greece				
	<p>● available at extra charge    ○ available at no extra charge    U annotations existing</p> <p>S standard equipment    - not available</p>				

[illegible][illegible]





From	Price list B-Class				
17-OKT-17	CY 17/2, MY 808+058, SR 23. October 2017				
	<table> <tr> <td>National Standard</td><td>National Package</td></tr> <tr> <td>Delta to NST</td><td>Not for Greece</td></tr> </table>	National Standard	National Package	Delta to NST	Not for Greece
National Standard	National Package				
Delta to NST	Not for Greece				
	<p>● available at extra charge    ○ available at no extra charge    ○ annotations existing</p> <p>S standard equipment    - not available</p>				

[illegible]

From	<b>Price list B-Class</b>
17-OKT-17	<b>CY 17/2, MY 808+058, SR 23. October 2017</b>
	<div> <div>National Standard</div> <div>Delta to NST</div> </div> <div> <div>National Package</div> <div>Not for Greece</div> </div>
	● available at extra charge    ○ available at no extra charge    ○ annotations existing S standard equipment    - not available

## National Package

Not for Greece

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]