

Valid from 23.10.2017 CY (808+058)

Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation		T	T	T	T	T	T	T	T	T	T	DLP
DB1	Progressive Plus Auto package National Package Included: 429-P49-P59-218-14U-175U / 191U / 589U / 149U / 696U / 761U / 787U / 890U / 895U / 990U		*					*					4495,00
DB2	Progressive Plus package National Package Included: P49-P59-218-14U-175U / 191U / 589U / 149U / 696U / 761U / 787U / 890U / 895U / 990U		*					*					2735,00
DB3	Offroad Auto package National Package Included: 429-P27-P49-218-30P-14U-400-482-175U / 191U / 589U / 149U / 696U / 761U / 787U / 890U / 895U / 990U		*					*					4480,00
DB4	Offroad package National Package Included: P27-P49-218-30P-14U-400-482-175U / 191U / 589U / 149U / 696U / 761U / 787U / 890U / 895U / 990U		*					*					2720,00
DB5	Sport package National Package Included: 950-218-14U-P49-857		*					*					3505,00
DB6	White Art Plus National Package Included: PEK-950-P49-P55-218-429-632		*					*					7680,00
L	Left-hand drive		O	O	O	O	O	O	O	O	O	O	0,00
R	Right-hand drive		*	*	*	*	*	*	*	*	*	*	1060,00
000U	paintwork not yet finalised only in conjunction with Code Z98 and 524		O	O	O	O	O	O	O	O	O	O	0,00
149U	polar white		O	O	O	O	O	O	O	O	O	O	0,00
175U	elbaite green metallic		*	*	*	*	*	*	*	*	*	*	590,00
191U	cosmos black metallic		*	*	*	*	*	*	*	*	*	*	590,00
589U	jupiter red		O	O	O	O	O	O	O	O	O	O	0,00
662U	designo mountain grey magno		*	*	*	*	*	*	*	*	*	*	1750,00
696U	nigh black only in conjunction with Code 524		O	O	O	O	O	O	O	O	O	O	0,00
761U	polar silver metallic		*	*	*	*	*	*	*	*	*	*	590,00
787U	mountain grey metallic		*	*	*	*	*	*	*	*	*	*	590,00
890U	cavansite blue metallic		*	*	*	*	*	*	*	*	*	*	590,00
895U	canyon beige metallic		*	*	*	*	*	*	*	*	*	*	590,00
896U	brilliant blue metallic certain countries only		-	-	-	-	-	-	-	-	-	-	590,00
990U	orient brown metallic		*	*	*	*	*	*	*	*	*	*	590,00
992U	selenite grey metallic certain countries only		*	*	*	*	*	*	*	*	-	*	590,00
996U	designo hyacinth red metallic certain countries only		*	*	*	*	*	*	*	*	-	*	1750,00
021A	Coari fabric black certain countries only not in conjunction with code 950, P27, P34, P59		O	O	O	O	O	O	O	O	-	O	0,00
028A	Coari fabric crystal grey certain countries only not in conjunction with code 950, P27, P34, P59		O	O	O	O	O	O	O	O	-	O	0,00
105A	ARTICO man-made leather sahara beige not in conjunction with code P34 or 950 only in conjunction with code P27 or P59 only in conjunction with code U59 in conjunction with Code P27 oder P59		*	*	*	*	*	*	*	*	-	*	260,00
			*	*	*	*	*	*	*	*	-	*	130,00
111A	ARTICO man-made leather black not in conjunction with code P34 or 950 only in conjunction with code U59 in conj. W. Code P27 oder P59		*	*	*	*	*	*	*	*	-	*	260,00
			*	*	*	*	*	*	*	*	-	*	130,00
118A	ARTICO man-made leather crystal grey not in conjunction with code P34 or 950 only in conjunction with code U59 in conj. W. Code P27 oder P59		*	*	*	*	*	*	*	*	-	*	260,00
			*	*	*	*	*	*	*	*	-	*	130,00
161A	black ARTICO man-made leather certain countries only only in conjunction with code P59; not in conjunction with U10		-	-	-	-	-	*	*	*	-	*	130,00
165A	almond beige / black ARTICO man-made leather certain countries only only in conjunction with code P59; not in conjunction with U10		-	-	-	-	-	*	*	*	-	*	130,00
168A	ARTICO man-made leather crystal grey certain countries only only in conjunction with code P59; not in conjunction with U10		-	-	-	-	-	*	*	*	-	*	130,00
175A	Kunstleder - beige / schwarz certain countries only not in conjunction with code U10 only in conjunction with code P59		-	-	-	-	-	*	*	*	-	*	130,00
378A	ARTICO man-made leather / Marinqá fabric crystal grey with white seams certain countries only not in conjunction with code P34 only in conjunction with code P59, U59		O	O	O	O	O	O	O	O	-	O	0,00
381A	ARTICO man-made leather / Marinqá fabric black with white seams certain countries only not in conjunction with code P34 only in conjunction with code P59, U59		O	O	O	O	O	O	O	O	-	O	0,00
411	6-speed manual transmission not in conjunction with code 238		S	S	-	-	-	S	S	O	-	-	0,00
429	7G-DCT - dual clutch automatic transmission AMG SPEEDSHIFT DCT 7-speed sports transmission		-	-	S	S	S	-	-	-	S	S	0,00
			*	*	-	-	*	U	*	*	-	*	1760,00

Valid from 23.10.2017 CY (808+058)

Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available - **BM 156.945 nur Indien (RL) or Korea (LL)**

[illegible]

GLA	
156.912	GLA 180 d Sport Utility Vehicle
156.908	GLA 200 d Sport Utility Vehicle
156.902	GLA 200 d 4MATIC Sport Utility Vehicle
156.903	GLA 220 d Sport Utility Vehicle
156.905	GLA 220 d 4MATIC Sport Utility Vehicle
156.942	GLA 180 Sport Utility Vehicle
156.943	GLA 200 Sport Utility Vehicle
156.944	GLA 250 Sport Utility Vehicle
156.946	GLA 250 4MATIC Sport Utility Vehicle
156.952	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle
156.945	GLA 200 Sport Utility vehicle RHD
156.947	GLA 220 4MATIC Sport Utility Vehicle

Valid from 23.10.2017 CY (808+058)

Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available - **BM 156.945 nur Indien (RL) or Korea (LL)**

Code	Description																	DLP
	only in conjunction with code P59,720,840, and 01R/655 or RV1 in conjunction with Code 950 I.V.m. Code P59	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	800,00
P59	Urban not in conjunction with code 950, P27 only in conjunction with code 280, R31/R48/01R/04R/48R/77R/65R/82R/635/655/RV1 or RVJ and (725 or 720+P55), 105A/111A/118A/161A/165A/168A/175A/381A,378A,801A,804A,811A/831A or 855A and 739/H73/H79/H81/ (or H06/H14/H19 and P34/P73) or U63	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1200,00
P60	AMG Night package only in conjunction with code 840 (cert. countries without 840) I.V.m. Code P74	-	-	-	-	-	-	-	-	-	-	●	-	-	-	-	-	670,00
P71	AMG DYNAMIC PLUS package consisting of code 281, 459 and 471 (certain countries only) in conjunction with 460/494 only in conjunction with 459, 471, 251 I.V.m. Code P74	-	-	-	-	-	-	-	-	-	-	●	-	-	-	-	-	2200,00
P73	Exclusive Comfort package certain countries only consisting of code 280, 873, (739/H06/H14/H19/H73/H54 and P27/(H79/H81) and P59/U63), U09, U22, 831A and (51U/58U) not in conjunction with code 950/U12/U26/P34 or P39 only in conjunction with code (880/889 or 893) I.V.m. Code P27 I.V.m. Code P59	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	2285,00
P74	Yellow Night Edition not in conjunction with code P34 or P39 only in conjunction with code (686U/191U) and RVW 691A, L6G, 555, 275, B26, U62, E74, 877 and (H92/H73) and (U66/498)	-	-	-	-	-	-	-	-	-	-	●	-	-	-	-	-	6400,00
PAH	AMG DINAMICA Cockpit package only in conjunction with code 651A or 811A, L6G and H92 I.V.m. Code P71	-	-	-	-	-	-	-	-	-	-	●	-	-	-	-	-	850,00
PEK	WhiteArt Edition certain countries only consisting of: 681A, H92/739, 280/277, U66/U26, 149U/761U/787U/191U/696U, and (U13/261) and RUG/RUH/633 or (655 only with P55) or (635 not with P55); RUG/RUH/655 with P55 available not in conjunction with code S8U/Y05/P34/P39/P59 or U63 only in conjunction with code 950 I.V.m. Code 555 I.V.m. Code 633 I.V.m. Code 633+555	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1200,00
U59	Seat comfort package not in conjunction with code 555 Standard I.V.m. P27/P34/P39/P59/P73/950	-	-	-	-	-	-	-	-	-	-	U	-	-	-	-	-	0,00
U62	Light and sight package certain countries only only in conjunction with Code 345, (543 (but not cert. countries)) and (U25 (but not cert. Countries)) I.V.m. Code 555 in conjunction with Code P27 I.V.m. Code P74 in conjunction with Code U63 in conjunction with Code P59, 950, P34, P39 and NOT 111A, 105A, 118A	U	U	U	U	U	U	U	U	U	U	U	U	U	U	U	U	290,00
U63	Driving school package certain countries only not inconjunction with code 840/P55/739/H06/H14/H19/H54/H73/H79 or H81 only in conjunction with code U59, U62, 931 only LHD in conjunction with Code U64	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	495,00
U90	Low-Line package China certain countries only	-	-	-	-	-	-	-	O	-	-	-	-	-	-	-	O	0,00
U92	High-Line-package China certain countries only	-	-	-	-	-	-	-	O	-	-	-	-	-	-	-	O	0,00
494	USA specification	-	-	-	-	-	-	-	-	O	O	O	O	O	O	O	-	0,00
498	Japan specification	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00
709	SKD vehicles for India	●	O	-	-	-	O	-	-	-	-	-	-	-	-	-	O	0,00
712	CKD delivery scope India only 623L	-	-	-	-	-	-	-	-	O	O	-	-	-	-	-	-	0,00
713	Omission of SKD parts Brazil	-	-	-	-	-	-	-	-	O	-	-	-	-	-	-	-	0,00
714	Omission of CKD parts Brazil	-	-	-	-	-	-	-	-	O	-	-	-	-	-	-	-	0,00
719	Indonesia SKD	-	-	-	-	-	-	-	-	O	-	-	-	-	-	-	-	0,00
00B	Owner's Manual and Service Booklet - Danish	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00
01B	Owner's Manual and Service Booklet - Dutch	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00
01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels in conjunction with code 645 not with R66 not in conjunction with code 950 in conjunction with Code P55 in conjunction with Code P59	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	610,00
02B	Owner's Manual and Service Booklet - German	O	O	O	O	O	O	O	O	O	O	O	O	O	O	S	S	0,00
03B	Owner's Manual and Service Booklet - Russian	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00
04B	Owner's Manual and Service Booklet - Finnish	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00
04R	45.7 cm (18-inch) multi-spoke light-alloy wheels certain countries only only in conjunction with code 645, R66 in conjunction with Code P55 or 950 in conjunction with Code P59	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	560,00
05B	Owner's Manual and Service Booklet - English	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	110,00
06B	Owner's Manual and Service Booklet - Italian	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00
07B	Owner's Manual and Service Booklet - French	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00
07U	MB apps for Audio 20 without MBCONNECT	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	50,00

Valid from 23.10.2017 CY (808+058)

Not for Greece

● available at extra charge O available at no extra charge U annotations existing
S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

Code	Description	1	1	1	1	1	1	1	1	1	1	1	1	DLP
	certain countries only not in conjunction with code 11U only in conjunction with code 505/520 or 522													
08B	Owner's Manual and Service Booklet - Spanish	o	o	o	o	o	o	o	o	o	o	o	o	0.00
08R	43.2 cm (17-inch) multi-spoke light-alloy wheels certain countries only not in conjunction with code R66/P55/P59/950 only in conjunction with code R01 or 645	s	s	s	s	s	s	s	s	-	s	s	s	0.00
09B	Owner's Manual and Service Booklet - Portuguese	o	o	o	o	o	o	o	o	o	o	o	o	0.00
10B	Owner's Manual and Service Booklet - Swedish	o	o	o	o	o	o	o	o	o	o	o	o	0.00
11B	Owner's Manual and Service Booklet - Arabic	o	o	o	o	o	o	o	o	o	o	o	o	0.00
11U	Remote Online certain countries only not in conjunction with code 07U only in conjunction with code 360 oder 362 I.V.m. Code 531/532	•	•	•	•	•	•	•	•	•	•	•	•	150.00
12B	Owner's Manual and Service Booklet - Engl. USA/CAN	o	o	o	o	o	o	o	o	o	o	o	o	0.00
12U	Concierge Service certain countries only	-	-	-	-	-	-	-	-	o	-	o	-	0.00
13B	Owner's Manual and Service Booklet - Norwegian	o	o	o	o	o	o	o	o	o	o	o	o	0.00
14B	Owner's Manual and Service Booklet - Greek	o	o	o	o	o	o	o	o	o	o	o	o	0.00
14U	Smartphone integration package not in conjunction with code 823L only in conjunction with code 16U and 17Ubut not in conjunction with code 823L I.V.m. Code 531/532	•	•	•	•	•	•	•	•	•	•	•	•	300.00
15B	Owner's Manual and Service Booklet - Turkish	o	o	o	o	o	o	o	o	o	o	o	o	0.00
15U	Pre-installation for Mercedes-Benz Link only in conjunction Code 505/520 or 522	o	o	o	o	o	o	o	o	o	o	o	o	0.00
16B	Owner's Manual and Service Booklet - Polish	o	o	o	o	o	o	o	o	o	o	o	o	0.00
16U	Apple CarPlay only in conjunction with code 14U	o	o	o	o	o	o	o	o	o	o	o	o	0.00
17B	Owner's Manual and Service Booklet - Czech	o	o	o	o	o	o	o	o	o	o	o	o	0.00
17U	Android Auto only in conjunction with code 14U	o	o	o	o	o	o	o	o	o	o	o	o	0.00
18B	Owner's Manual and Service Booklet - Engl. S. Am.	o	o	o	o	o	o	o	o	o	o	o	o	0.00
18U	Baidu Carlife certain countries only	-	-	-	-	-	-	o	-	o	-	o	-	0.00
19B	Owner's Manual and Service Booklet - French S. Am.	o	o	o	o	o	o	o	o	o	o	o	o	0.00
1R0	winter (M+S) wheel and tyre assembly x 4 not in conjunction with code R66 only Germany	•	•	•	•	•	•	•	•	•	•	•	•	950.00
1R7	winter (M+S) wheel and tyre assembly x 4 not in conjunction with code R66 only Germany	•	•	•	•	•	•	•	•	•	-	•	•	1410.00
20B	Owner's Manual and Service Booklet - Spanish S. Am.	o	o	o	o	o	o	o	o	o	o	o	o	0.00
210	Literature in Swedish	o	o	o	o	o	o	o	o	o	o	o	o	0.00
213	Sports Direct-Steer system certain countries only only in conjunction with code 486/459	o	o	o	o	o	o	o	o	o	-	o	o	0.00
218	Reversing camera not in conjunction with code 501	•	•	•	•	•	•	•	•	•	•	•	•	335.00
21B	Owner's Manual and Service Booklet - Portug. S. Am.	o	o	o	o	o	o	o	o	o	o	o	o	0.00
228	Auxiliary heater certain countries only certain countries only in conjunction with code B24 only LHD I.V.m. Code 360/362	•	•	•	•	•	•	•	•	•	-	•	•	1250.00
22B	Owner's Manual and Service Booklet - Japanese	•	•	•	•	•	•	•	•	•	-	•	•	1100.00
232	Garage door opener (frequency range 284-390 MHz) certain countries only only in conjunction with code U62, P49 (cert.countries only)	•	•	•	•	•	•	•	•	•	•	•	•	225.00
234	Blind Spot Assist certain countries only In conjunction with Code 22P	•	•	•	•	•	•	•	•	•	•	•	•	450.00
235	Parking Pilot I.V.m. Code P44	o	o	o	o	o	o	o	o	o	o	o	o	0.00
239	Distance Pilot DISTRONIC certain countries only not in conjunction with code 258 or 440 only in conjunction with code 429	•	•	•	•	•	•	•	•	•	•	•	•	675.00
23B	Owner's Manual and Service Booklet - simpl. Chinese	o	o	o	o	o	o	o	o	o	o	o	o	0.00
241	Front seat left, elect.adjust.w.mem. switch only in conjunction with code 275 right-hand-drive vehicles only I.V.m. Code 555 I.V.m. Code P74	•	•	•	•	•	•	•	•	•	•	•	•	285.00
242	Front pass. seat, electrically adj. with memory function LHD version not in conjunction with code 842 only in conjunction with code 275 In conjunction with Code 555 I.V.m. Code P74	o	o	o	o	o	o	o	o	o	o	o	o	0.00
245	Compass certain countries only not in conjunction with code 531 only in conjunction with code U62 and P49 (certain countries only)	•	•	•	•	•	•	•	•	•	•	•	•	105.00
249	Interior mirror and driver's exterior mirror automatically dimming certain countries only	o	o	o	o	o	o	o	o	o	o	o	o	0.00

17/10/2017 Optional extras for the GLA

Valid from 23.10.2017 CY (808+058)

National Package
National Standard
Delta to NST
Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.912	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	DLP
	only in conjunction with code P49													
24B	Owner's Manual and Service Booklet - trad. Chinese	○	○	○	○	○	○	○	○	○	○	○	○	0,00
250	AMG Driver's package certain countries only	-	-	-	-	-	-	-	-	-	●	-	-	1400,00
	I.V.m. Code 146	-	-	-	-	-	-	-	-	-	●	-	-	1400,00
251	Increase in top speed, USA certain countries only	-	-	-	-	-	-	-	-	-	-	-	-	1400,00
258	Active Brake Assist certain countries only not in conjunction with code 239	S	S	S	S	S	S	S	S	S	S	S	S	0,00
25B	Owner's Manual and Service Booklet - Korean	○	○	○	○	○	○	○	○	○	○	○	○	0,00
260	Deletion of model plate on boot lid certain countries only	○	○	○	○	○	○	○	○	○	○	○	○	0,00
261	Omission of badge not in conjunction with code U13 only in conjunction with code PEK	U	U	U	U	U	U	U	U	U	○	U	○	0,00
263	Number plate mounting for Asia / Mexico	○	○	○	○	○	○	○	○	○	○	○	○	0,00
264	Number plate mounting for America	○	○	○	○	○	○	○	○	○	○	○	○	0,00
26B	Owner's Manual and Service Booklet - Chinese Taiwan	○	○	○	○	○	○	○	○	○	○	○	○	0,00
275	Driver's seat, electrically adjustable with memory function in conjunction with code 555 only in conjunction with code 651A/681A/691 or 801A/804A/811A or 855A only in conjunction with code U22, U59 (not conjunction with 555) I.V.m. Code 555	●	●	●	●	●	●	●	●	●	●	●	●	345,00
	I.V.m. Code P74	-	-	-	-	-	-	-	-	-	●	-	-	525,00
277	multifunction sports steering wheel in leather with perforations in the grip area only in conjunction with PEK	○	○	○	○	○	○	○	○	○	○	○	○	0,00
280	Leather multifunction steering wheel multifunction sports steering wheel leather, flattened bottom section, black DINAMICA in grip area (i.c.w. PEK) multifunction sports steering wheel, leather (i.c.w. P39/950) I.V.m. Code PEK I.V.m. P27/P34/P39/P59/P73/950	●	●	●	●	●	●	●	●	●	-	●	●	175,00
	I.V.m. P27/P34/P39/P59/P73/950	○	○	○	○	○	○	○	○	○	-	○	○	0,00
281	AMG Performance steering wheel AMG Performance steering wheel I.V.m. Code P71	-	-	-	-	-	-	-	-	-	○	-	-	420,00
	I.V.m. Code P71	-	-	-	-	-	-	-	-	-	○	-	-	0,00
286	Luggage net on driver's and front pass. backrest certain countries only not in conjunction with code 555 only in conjunction with code 30P	○	○	○	○	○	○	○	○	○	○	○	○	0,00
290	Windowbags	S	S	S	S	S	S	S	S	S	S	S	S	0,00
293	Sidebags in rear certain countries only	U	U	U	U	U	U	U	U	U	○	U	○	375,00
294	Kneebags certain countries only	○	○	○	○	○	○	○	○	○	○	○	○	0,00
299	PRE-SAFE® system certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	330,00
2R4	complete winter (M+S) wheel-and-tyre assembly x 4 not in conjunction with code R66 only Germany	●	●	●	●	●	●	●	●	●	-	●	●	1860,00
2U0	Car2Go wiring harness and coding not in conjunction with code 865	●	●	●	●	●	●	●	●	●	●	●	●	15,00
301	Front and rear ashtray inserts in the stowage compartments as well as cigarette lighter in the front certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	45,00
309	Cup holder only in conjunction with code 429	○	○	○	○	○	○	○	○	○	-	○	○	0,00
30B	Owner's Manual and Service Booklet - Slovenian	○	○	○	○	○	○	○	○	○	○	○	○	0,00
310	Cup holder certain countries only	-	-	-	-	-	-	-	-	-	●	-	-	25,00
31B	Owner's Manual and Service Booklet - Hungarian	○	○	○	○	○	○	○	○	○	○	○	○	0,00
32B	Owner's Manual and Service Booklet - Bulgarian	○	○	○	○	○	○	○	○	○	○	○	○	0,00
33B	Owner's Manual and Service Booklet - Romanian	○	○	○	○	○	○	○	○	○	○	○	○	0,00
345	Windscreen wiper with rain sensor only in conjunction with code U62	○	○	○	○	○	○	○	○	○	○	○	○	0,00
34B	Owner's Manual and Service Booklet - Croatian	○	○	○	○	○	○	○	○	○	○	○	○	0,00
351	Mercedes-Benz emergency call system certain countries only only in conjunction with code 360 or 362	○	○	○	○	○	○	○	○	○	○	○	○	0,00
357	Garmin® MAP PILOT certain countries only only in conjunction with code 522	●	●	●	●	●	●	●	●	●	●	●	●	500,00
35B	Owner's Manual and Service Booklet - Latvian	○	○	○	○	○	○	○	○	○	○	○	○	0,00
360	Communications module (UMTS) only in conjunction with code 505/520/522 or 531	S	S	S	S	S	S	S	S	S	S	S	S	0,00
362	Communications module (LTE) certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	150,00
367	Live Traffic Information certain countries only in cert. Countries only in conjunction with code 362 and 531 only in conjunction with code 360, (522 oder 531)	○	○	○	○	○	○	○	○	○	○	○	○	0,00
36B	Owner's Manual and Service Booklet - Lithuanian	○	○	○	○	○	○	○	○	○	○	○	○	0,00
379	Car telephony not in conjunction with code 386 only certain countries	●	●	●	●	●	●	●	●	●	●	●	●	700,00
37B	Owner's Manual and Service Booklet - Slovakian	○	○	○	○	○	○	○	○	○	○	○	○	0,00
386	Universal Telephony package certain countries only not in conjunction with code 379/460/494/498/536/537/865 only in conjunction with code 505/520/522/531	●	●	●	●	●	●	●	●	●	●	●	●	400,00
38B	Owner's Manual and Service Booklet - Estonian	○	○	○	○	○	○	○	○	○	○	○	○	0,00
39B	Owners manual and service record - Serbian	○	○	○	○	○	○	○	○	○	○	○	○	0,00
3R9	complete winter (M+S) wheel-and-tyre assembly x 4	●	●	●	●	●	●	●	●	●	-	●	●	1850,00

Valid from 23.10.2017 CY (808+058)

Not for Greece

● available at extra charge O available at no extra charge U annotations existing
S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

[illegible]

17/10/2017 Optional extras for the GLA

Valid from 23.10.2017 CY (808+058)

National Package
National Standard
Delta to NST
Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

GLA
156.912 GLA 180 d Sport Utility Vehicle
156.908 GLA 200 d Sport Utility Vehicle
156.902 GLA 200 d 4MATIC Sport Utility Vehicle
156.903 GLA 220 d Sport Utility Vehicle
156.905 GLA 220 d 4MATIC Sport Utility Vehicle
156.942 GLA 180 Sport Utility Vehicle
156.943 GLA 200 Sport Utility Vehicle
156.944 GLA 250 Sport Utility Vehicle
156.946 GLA 250 4MATIC Sport Utility Vehicle
156.952 Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle
156.945 GLA 200 Sport Utility Vehicle RHD
156.947 GLA 220 4MATIC Sport Utility Vehicle

Code	Designation	156.912	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	DLP
	only in conjunction with code 815 or 14U													
536	Sirius satellite radio certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	350,00
537	Digital radio (only certain countries) & not in conjunction with code Z97 only in conjunction with code 505/522/531	●	●	●	●	●	●	●	●	●	●	●	●	425,00
538	ATTENTION ASSIST	S	S	S	S	S	S	S	S	S	S	S	S	0,00
543	Sun visor with illuminated vanity mirror only in conjunction with code U62	○	○	○	○	○	○	○	○	○	○	○	○	0,00
550	Trailer coupling with ESP® trailer stabilisation certain countries only not in conjunction with code 459	U	U	U	U	U	U	U	U	U	-	U	U	790,00
551	Anti-theft alarm system only in conjunction with code P54 (certain countries only) in conjunction with Code P54	●	●	●	●	●	●	●	●	●	●	●	●	250,00
552	Anti-theft warning system only in conjunction with code P54 and 513L	○	○	○	○	○	○	○	○	○	○	○	○	0,00
555	AMG Performance seats in conjunction with code 651A only in conjunction with U10 in conjunction with code 801A/804A/811A or 691A only in conjunction with code 275, 241/242 and U10 not in conjunction with code U22, U59 only in conjunction with code 651A/681A/801A/804A/808A/811A only in conjunction with code PEK and only in conjunction with code 681A and U10 i.V.m. Code P74	U	U	U	U	U	U	U	U	U	U	U	U	1800,00
	i.V.m. Code PEK	●	●	●	●	●	●	●	●	●	●	●	●	0,00
55U	Roof liner beige fabric not in conjunction with code P73 only in conjunction with code P27 and (105A/625A) or P34 with 855A or P59 with 105A/165A/175A	○	○	○	○	○	○	○	○	○	○	○	○	0,00
580	Air conditioning system certain countries only	S	S	S	S	S	S	S	S	S	S	S	S	0,00
581	THERMOTRONIC automatic climate control certain countries only only in conjunction with code P27/P34/P59/P73 or 950	●	●	●	●	●	●	●	●	●	●	●	●	510,00
58U	Roof liner in crystal grey fabric in conjunction with P34 only in conjunction with code 801A oder P73 not in conjunction with code P27 with code 105A/604A/625A or P59 not with code 105A/165A/175A or 950/P34 or P73	○	○	○	○	○	○	○	○	○	○	○	○	0,00
5R1	complete winter (M+S) wheel-and-tyre assembly x 4 not in conjunction with code R66 only Germany	●	●	●	●	●	●	●	●	●	-	●	●	1860,00
608	Adaptive Highbeam Assist only in conjunction with code 631 or 632	●	●	●	●	●	●	●	●	●	●	●	●	100,00
613	Headlamps for RHD vehicles certain countries only part of standard specification for LHD countries	○	○	○	○	○	○	○	○	○	-	○	○	0,00
620	Halogen headlamps including integral LED daytime running lamps	○	○	○	○	○	○	○	○	○	-	○	○	0,00
623	Gulf States specification	-	-	-	-	-	-	-	-	-	○	-	-	0,00
625	Australia specification	-	-	-	-	-	-	-	-	-	○	-	-	0,00
631	LED High Performance headlamp (RHD) only for certain countries Standard (cert. Countries only)	●	●	●	●	●	●	●	●	●	○	●	●	0,00
632	LED High Performance headlamp only for certain countries Standard (cert. Countries only)	●	●	●	●	●	●	●	●	●	○	●	●	875,00
633	45.7 cm (18-inch) AMG 5-spoke light-alloy wheels certain countries only in conjunction with code 645 not in conjunction with R66 not in conjunction with code P55 only in conjunction with Code 950	○	○	○	○	○	○	○	○	○	-	○	○	0,00
634	Omission of first-aid kit certain countries only not in conjunction with code 820	○	○	○	○	○	○	○	○	○	○	○	○	0,00
635	48.3 cm (19-inch) AMG 5-spoke light-alloy wheels certain countries only in conjunction with code 645 not in conjunction with R66 in conjunction with code R01/R02 only in conjunction with code R66 not in conjunction with code P55 in conjunction with Code 950 in conjunction with Code P59 i.V.m. Code PEK	●	●	●	●	●	●	●	●	●	-	●	●	1300,00
		●	●	●	●	●	●	●	●	●	-	●	●	450,00
		○	○	○	○	○	○	○	○	○	-	○	○	850,00
		○	○	○	○	○	○	○	○	○	-	○	○	0,00
636	Omission of warning triangle not in conjunction with code 820	○	○	○	○	○	○	○	○	○	○	○	○	0,00
645	M+S winter tyres, set of 4 not in conjunction with code 460, 494, 498, 625, or 830 only in conjunction with code R00/R48/08R/633/R31/01R/82R/48R/65R/77R/635/655/RVJ/RVJ/RUG or RUH but not with code R66 or 04R with code R66	●	●	●	●	●	●	●	●	●	-	●	●	110,00
651	Winter complete wheels fitted only in conjunction with code 1R0/1R7/2R4/3R9/4R6/5R1 or 8R4	○	○	○	○	○	○	○	○	○	○	○	○	0,00
652	Summer complete tyres fitted only in conjunction with code 1R0/1R7/2R4/3R9/4R6/5R1 or 8R4	○	○	○	○	○	○	○	○	○	○	○	○	0,00
655	48.3 cm (19-inch) AMG 5-spoke light-alloy wheels certain countries only in conjunction with code R01/R02 only in conjunction with code R66 in conj. with 950 and P55 in conjunction with Code 950 in conjunction with Code P55 in conjunction with Code P59 i.V.m. Code PEK	●	●	●	●	●	●	●	●	●	-	●	●	1300,00
		○	○	○	○	○	○	○	○	○	-	○	○	0,00
		●	●	●	●	●	●	●	●	●	-	●	●	450,00
		●	●	●	●	●	●	●	●	●	-	●	●	690,00
		●	●	●	●	●	●	●	●	●	-	●	●	850,00
		○	○	○	○	○	○	○	○	○	-	○	○	0,00
65R	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels	●	●	●	●	●	●	●	●	●	-	●	●	910,00

17/10/2017 Optional extras for the GLA

Valid from 23.10.2017 CY (808+058)

National Package
National Standard
Delta to NST
Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

GLA
156.912 GLA 180 d Sport Utility Vehicle
156.908 GLA 200 d Sport Utility Vehicle
156.902 GLA 200 d 4MATIC Sport Utility Vehicle
156.903 GLA 220 d Sport Utility Vehicle
156.905 GLA 220 d 4MATIC Sport Utility Vehicle
156.942 GLA 180 Sport Utility Vehicle
156.943 GLA 200 Sport Utility Vehicle
156.944 GLA 250 Sport Utility Vehicle
156.946 GLA 250 4MATIC Sport Utility Vehicle
156.952 Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle
156.945 Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle RHD
156.947 GLA 220 4MATIC Sport Utility Vehicle

Code	Designation	156.912	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	DLP
	in conjunction with code R01/R02 only in conjunction with code R66 not in conjunction with code 950, 951 in conjunction with Code P55 in conjunction with Code P59	●	●	●	●	●	●	●	●	●	●	●	●	300.00 460.00
666	Freight packaging without tie-down hooks certain countries only not in conjunction with code 820 in conjunction with Code 14P, 15P or 16P	●	●	●	●	●	●	●	●	●	●	●	●	25.00 0.00
668	Prod. prot. f. freight pkaging with tie-down hooks certain countries only not in conjunction with code 820 in conjunction with Code 14P, 15P or 16P	●	●	●	●	●	●	●	●	●	●	●	●	25.00 0.00
669	Collapsible spare wheel certain countries only; Standard certain countries only only in conjunction with code E76 and B12	-	-	-	-	-	-	-	-	-	-	-	-	0.00
682	Fire extinguisher NATIONAL STANDARD certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	110.00
687	Type plate with model year certain countries only Standard certain countries only	○	○	○	○	○	○	○	○	○	○	○	○	0.00
690	Pre-installation for the spare wheel certain countries only; Standard certain countries only only in conjunction with code E76 and B12	○	○	○	○	○	○	○	○	○	-	○	○	0.00
700	Produktionsstandort Fahrzeug China only 813L	-	-	-	-	-	-	○	-	○	-	-	○	0.00
70B	Fluorescent jacket for driver certain countries only not in conjunction with code 71B	●	●	●	●	●	●	●	●	●	●	●	●	5.00
71B	Fluorescent jackets for driver and passengers not in conjunction with code 70B or 830	●	●	●	●	●	●	●	●	●	●	●	●	25.00
720	Aluminium roof rails in high-gloss black in conjunction with code 950, P59 only in conjunction with code P55 only in conjunction with code P60 in conjunction with Code P27 oder P55	-	●	-	-	-	-	-	-	○	-	-	-	0.00 225.00 0.00
725	Aluminium roof rails not in conjunction with code P55 not in conjunction with code P60 only in conjunction with code 950, P59	○	○	○	○	○	○	○	○	○	○	○	○	0.00
739	aluminium trim with trapeze cut certain countries only only in conjunction with code P59 oder P73 but not with code U63 or PEK only in conjunction with code PEK and 950	○	○	○	○	○	○	○	○	○	-	○	○	0.00
754	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels not in conjunction with code R66 only in conjunction with code R01	-	-	-	-	-	-	-	-	-	S	-	-	0.00
758	50.8 cm (20-inch) AMG 10-spoke light-alloy wheels not in conjunction with code R66 only in conjunction with code R01	-	-	-	-	-	-	-	-	-	●	-	-	600.00
762	Remote control unit	○	○	○	○	○	○	○	○	○	○	○	○	0.00
763	Key with Radio remote control with panic switch only in conjunction with Code 551 and certain countries only	○	○	○	○	○	○	○	○	○	○	○	○	0.00
772	AMG bodystyling not in conjunction with code U37 only in conjunction with code 950 or 951	○	○	○	○	○	○	○	○	○	S	○	○	0.00
778	50.8 cm (20-inch) AMG 10-spoke light-alloy wheels not in conjunction with code R66 only in conjunction with code R01	-	-	-	-	-	-	-	-	-	●	-	-	950.00
77R	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels certain countries only not in conjunction with code 460, 494, P55, 950 only in conjunction with code R01 and R66 in conjunction with Code P59	●	●	●	●	●	●	●	●	●	-	●	●	750.00
808	Technical modifications	○	○	○	○	○	○	○	○	○	○	○	○	300.00
810	Harman Kardon® Logic 7® surround sound system not in conjunction with code 520 only in conjunction with code 505/522/531/532	●	●	●	●	●	●	●	●	●	●	●	●	685.00
814	DVD changer only in conjunction with code 531	●	●	●	●	●	●	●	●	●	●	●	●	300.00
815	DVD player only in conjunction with code 531 or 532	○	○	○	○	○	○	○	○	○	○	○	○	0.00
818	CD player only in conjunction with code 505 or 522	○	○	○	○	○	○	○	○	○	○	○	○	0.00
820	Tourist vehicles certain countries only not in conjunction with code 634, 636, 666 or 668	○	○	○	○	○	○	○	○	○	○	○	○	0.00
821	Country code Brazil	-	-	-	-	-	-	○	○	○	○	-	-	0.00
822	South Africa specification	○	○	○	○	○	○	○	○	○	○	○	○	0.00
823	Indicator plate fixing Switzerland	○	○	○	○	○	○	○	○	○	○	○	○	0.00
824	Additional parts for cold countries certain countries only; Standard certain countries only	○	○	○	○	○	○	-	-	-	-	-	-	0.00
829	Taiwan version	○	○	○	○	○	○	○	○	○	○	○	○	0.00
82R	45.7 cm (18-inch) 5-spoke light-alloy wheels certain countries only in conjunction with code 645 not with code R66 not in conjunction with code 950/951or P55 i.V.m. Code P59	●	●	●	●	●	●	●	●	●	-	●	●	450.00
830	China specification	-	-	-	-	-	-	○	○	○	○	-	○	0.00

Valid from 23.10.2017 CY (808+058)

Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available - **BM 156.945 nur Indien (RL) or Korea (LL)**

Optional extras for the GLA

Valid from 23.10.2017 CY (808+058)

National Package

National Standard

Delta to NST

Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	GLA 180 d Sport Utility Vehicle	GLA 200 d Sport Utility Vehicle	GLA 200 d 4MATIC Sport Utility Vehicle	GLA 220 d Sport Utility Vehicle	GLA 220 d 4MATIC Sport Utility Vehicle	GLA 180 Sport Utility Vehicle	GLA 200 Sport Utility Vehicle	GLA 250 Sport Utility Vehicle	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle	GLA 220 4MATIC Sport Utility Vehicle RHD	DLP
831	Indicator plate fixing Italia	○	○	○	○	○	○	○	○	○	○	0.00
835	South Korea specification	○	○	○	○	○	○	○	○	○	○	0.00
840	Heat-insulating dark-tinted glass certain countries only not in conjunction with code U63 in conjunction with Code P55, P60	●	●	●	●	●	●	●	●	●	●	270.00
842	Folding front passenger seat not in conjunction with code 242 only in conjunction with code U59, 942 and 021 A/028 A/105 A/11 A/118 A/621 A/625 A/631 A only LHD models	○	○	○	○	○	○	○	○	-	○	0.00
857	Media-Display only in conjunction with code 505/520 or 522	●	●	●	●	●	●	●	●	●	●	160.00
862	Preinstallation for TV certain countries only only in conjunction with code 531 or 532	●	●	-	-	-	-	-	-	■	●	80.00
865	TV receiver certain countries only not in conjunction with code 2U0 only in conjunction with code 532 or 532	●	●	-	-	-	-	-	-	●	●	990.00
871	HANDS-FREE ACCESS only in conjunction with code P17, 889 and 890	○	○	○	○	○	○	○	○	○	○	0.00
873	Heated front seats i.V.m. Code P34/P39/P73	●	●	●	●	●	●	●	●	●	●	290.00
875	Heated windshield washer system certain countries only	U	●	●	U	●	●	●	U	●	●	115.00
877	Ambient lighting only in conjunction with code U62 and P27/P34/ P39/P59/P73 or 950 i.V.m. Code P74	★	U	★	U	★	U	★	U	★	★	120.00
882	Interior monitoring system certain countries only only in conjunction with code P54	○	○	○	○	○	○	○	○	○	○	0.00
885	Increased anti-theft protection only 537L	○	○	○	○	○	○	○	○	○	○	0.00
889	KEYLESS-GO certain countries only not in conjunction with code 880 or 893 i.V.m. Code P17	●	●	●	●	●	●	●	●	●	●	450.00
890	EASY-PACK tailgate i.V.m. Code P17	○	○	○	○	○	○	○	○	○	○	0.00
893	KEYLESS GO starting function certain countries only not in conjunction with code 880 oder 889	S	S	S	S	S	S	S	S	S	S	390.00
894	Complete winter (W+S) wheel-and-tyre assembly x 4	-	-	-	-	-	-	-	-	●	-	2700.00
913	Air conditioning preinstallation for hot countries certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
922	Reduced power version only in conjunction with code 513L only in conjunction with code 524L	-	-	-	U	★	U	-	-	-	-	0.00
926	Emission control system with EU4 technology certain countries only	○	○	-	○	○	○	○	○	○	S	0.00
927	EU6 emissions standard certain countries only	S	S	S	S	S	S	S	S	S	○	0.00
928	EU5 emission standard certain countries only	-	-	-	-	○	○	-	○	-	S	0.00
929	Ethanol fuelled engine certain countries only	-	-	-	-	-	-	○	-	-	○	0.00
931	Tandem interior mirror only in conjunction with code U63 (only LHD)	○	○	○	○	○	○	○	○	○	○	0.00
932	Storage compartment front seat left not in conjunction with code 555 not in conjunction with code 682 (only LHD) only in conjunction with code 30P	○	○	○	○	○	○	○	○	U	○	0.00
933	Engine for ethanol fuel E100	-	-	-	-	-	●	-	-	-	-	300.00
939	Stowage box under front passenger seat not in conjunction with code 555 not in conjunction with code 682 (only RHD) only in conjunction with code 30P	○	○	○	○	○	○	○	○	U	○	0.00
942	Load compartment package in conjunction with code 021 A/028 A/105 A/11 A/118 A/621 A/625 A or 631 A only with 842 or 242 (RHD not with 842) in conjunction with code 381 A/378 A/651 A/801 A/804 A/811 A/831 A/855 A, not in conjunction with code 842 only in conjunction with code U35 i.V.m. Code 242/950/P34/P73 i.V.m. P59 ohne 105 A/111 A/118 A	-	●	●	-	●	●	-	●	●	●	145.00 200.00
945	Emission control system China certain countries only	-	-	-	-	-	○	-	○	○	-	0.00
968	COC document EU6 without registration certificate part II certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
969	COC document EU6 with registration certificate part II certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
973	Designation as owner-driver rental vehicle	○	○	○	○	○	○	○	○	○	○	0.00
981	Omission of vehicle registration document	○	○	○	○	○	○	○	○	○	○	0.00
986	Identification no. (US-VIN) certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
989	Identification label under windshield certain countries only; Standard certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
997	Exhibition vehicle certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
B02	Fanfare horn, electronic, for India	○	○	○	○	○	○	○	○	-	S	0.00

Valid from 23.10.2017 CY (808+058)

Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available - **BM 156.945 nur Indien (RL) or Korea (LL)**

Code	Description																DLP
B03	ECO start/stop function	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0.00
B08	Fanfare horn certain countries only	U	U	U	U	U	U	U	U	S	U	S					0.00
B12	Tyre-change toolkit (certain countries only) only in conjunction with code 690	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	30.00
B24	remote control for auxiliary heater certain countries only only in conjunction with code 228 i.V.m. Code 360/362	O	O	O	O	O	O	O	O	-	O	O					0.00
B28	AMG carbon-fibre exterior mirrors certain countries only not in conjunction with code 501 oder P44	U	*	*	*	*	*	U	U	U	*	*	*	*	*	*	200.00
B51	TIREFIT with tyre inflation compressor certain countries only in conjunction with code 645 only in conjunction with code 01R/65R/77R/R31/633/635/655 RV1 or RVJ (cert. countries only) not in conjunction with code R08 (certain countries only) i.V.m. Code 360	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0.00
B59	DYNAMIC SELECT AMG DYNAMIC SELECT i.V.m. Code 429/459/486/950	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	80.00
E64	ECALL RUSSLAND (GLONASS)	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0.00
E74	Adhesive film only in conjunction with P74	-	-	-	-	-	-	-	-	-	O	-	-	-	-	-	0.00
E76	Spare wheel certain countries only only in conjunction with code 669 only in conjunction with code 690	U	U	U	U	U	U	U	U	U	U	U	U	U	U	*	250.00
H06	matt black ash wood trim certain countries only not in conjunction with code U63 only in conjunction with code 950/P34/P27 or P73 only LHD i.V.m. Code P34/P73	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	260.00
H14	high-gloss brown burr walnut wood trim certain countries only not in conjunction with code U63 Only in conjunction with code P34, P27 or P73 only LHD i.V.m. Code P34/P73	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0.00
H19	Satin-finish light brown poplar wood trim certain countries only not in conjunction with code U63 only in conjunction with code P34, P27 or P73 only LHD i.V.m. Code P34/P73	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	260.00
H54	Black matrix-look trim not in conjunction with code U63 or PEK only in conjunction with code P27	O	O	O	O	O	O	O	O	O	O	-	O	O	O		0.00
H73	AMG carbon-fibre trim not in conjunction with code U63 only in conjunction with code 950/P27/P34/P39/P59/P73 or P74 (only AMG-Type) i.V.m. Code P74	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	900.00
H79	light aluminium trim with longitudinal grain certain countries only in conjunction with code 950 not in conjunction with code PEK/U63 in conjunction with code P34 or P39 not in conjunction with code U63 (RHD) or Mercedes-AMG GLA 45 in conjunction with code P59 not in conjunction with code U63 and cert. Countries only i.V.m. Code P34/P39/P73/950	-	*	*	*	*	*	*	*	*	*	*	*	*	*	*	0.00
H81	Sail-pattern trim certain countries only not in conjunction with code U63 only in conjunction with code P59	O	O	O	O	O	O	O	O	O	O	-	O	O	O		0.00
H90	AMG Design trim in black / red not in conjunction with code P74 or P34	-	-	-	-	-	-	-	-	-	-	S	-	-	-	-	0.00
H91	AMG Design trim in black / silver not in conjunction with code P74 and certain countries only only in conjunction with code P34	-	-	-	-	-	-	-	-	-	-	O	-	-	-	-	0.00
H92	AMG trim in black DINAMICA microfibre certain countries only not in conjunction with code P34 only in conjunction with code 651A or 811A or (PEK with 950) or P74 only in conjunction with code 950/951 or P39 only with 651A or 811A i.V.m. Code PAH/P74 i.V.m. Code PEK	U	U	U	U	U	U	U	U	U	U	U	U	U	U	U	260.00
K08	Radio frequencies for South America certain countries only only in conjunction with code 505/520/522/531	-	*	*	*	*	*	*	*	*	*	*	*	*	*	*	0.00
K11	Adaptive brake lights certain countries only	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0.00
L6G	AMG Performance steering wheel, microfibre DINAMICA black only in conjunction with code 651A or 691A or 811A i.V.m. Code P71 i.V.m. Code PAH/P74	-	-	-	-	-	-	-	-	-	-	*	-	-	-	-	520.00
R00	43.2 cm (17-inch) steel wheels with 10-hole trim certain countries only not in conjunction with code P27, P55, P59, R66, 830, 950,951 only in conjunction with code R01 or 645	-	-	-	-	-	-	-	-	-	-	*	-	-	-	-	150.00
		O	O	O	O	O	O	O	O	O	O	-	O	O	O		0.00

Valid from 23.10.2017 CY (808+058)

Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

[illegible]

Valid from 23.10.2017 CY (808+058)

Not for Greece

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available - **BM 156.945 nur Indien (RL) or Korea (LL)**

[illegible]